

**INSPECTION REPORT
OF
ASBESTOS AND LEAD-BASED PAINTED
BUILDING MATERIALS**

**CAPEHART FAMILY HOUSING IMPROVEMENTS
MALMSTROM AIR FORCE BASE
GREAT FALLS, MONTANA**

**INSPECTION REPORT
OF
ASBESTOS AND LEAD-BASED PAINTED
BUILDING MATERIALS**

**CAPEHART FAMILY HOUSING IMPROVEMENTS - PHASE 3
MALMSTROM AIR FORCE BASE
GREAT FALLS, MONTANA**

Prepared by:

**MAXIM TECHNOLOGIES, INC.
303 IRENE STREET
HELENA, MONTANA**

Project No. 9900589-100

October 21, 1999

TABLE OF CONTENTS

	<u>Page No.</u>
1.0 INTRODUCTION	1
1.1 SCOPE OF WORK.....	1
1.2 QUALITY ASSURANCE AND QUALITY CONTROL	1
1.3 DRAWING DEVELOPMENT.....	2
2.0 ASBESTOS INSPECTION	3
2.1 ASBESTOS OVERVIEW.....	3
2.2 PROCEDURES	3
2.2.1 Inspection and Sampling.....	4
2.2.2 Laboratory Analysis	6
2.2.3 NESHAP Categories	6
3.0 LEAD-BASED PAINT INSPECTION.....	7
3.1 LEAD-BASED PAINT OVERVIEW.....	7
3.2 PROCEDURES	7
3.2.1 Inspection and Sampling.....	7
3.2.2 XRF Sampling Methodology.....	8
3.2.3 Summary of Lead-Based Paint	8
4.0 FINDINGS	9
4.1 CAPEHART FAMILY HOUSING UNITS.....	9
4.2 HOUSING UNIT INSPECTION SUMMARY	9
4.2.1 #11 Aspen Street.....	10
4.2.2 #12 Aspen Street.....	11
4.2.3 #2 Cedar Street	12
4.2.4 #12 Birch Street.....	13
5.0 LIMITATIONS	14
5.1 ASBESTOS.....	14
5.2 LEAD-BASED PAINT.....	15

LIST OF APPENDICES

- APPENDIX A** REGULATORY REVIEW FOR ASBESTOS AND LEAD-BASED PAINTED BUILDING COMPONENTS
- APPENDIX B** MAXIM PERSONNEL AHERA AND LEAD INSPECTOR CERTIFICATES
- APPENDIX C** ACBM BULK SAMPLE LABORATORY RESULTS
- APPENDIX D** ASBESTOS HOMOGENEOUS AREA DIAGRAMS
- APPENDIX E** PHOTOGRAPHS OF HOMOGENEOUS ASBESTOS-CONTAINING BUILDING MATERIALS
- APPENDIX F** LEAD-BASED PAINT XRF TEST RESULTS
- APPENDIX G** LEAD-BASED PAINT HOMOGENEOUS AREA DIAGRAMS
- APPENDIX H** PHOTOGRAPHS OF HOMOGENEOUS LEAD-BASED PAINTED BUILDING MATERIALS

**ASBESTOS AND LEAD BASED PAINT INSPECTION REPORT
MALMSTROM AIR FORCE BASE**

Capehart Family Housing Improvements – Phase 3

1.0 INTRODUCTION:

1.1 SCOPE OF WORK

The purpose of this inspection of the Capehart Family Housing, at Malmstrom Air Force Base, in Great Falls, Montana, was to identify friable and nonfriable known or suspect asbestos-containing building materials (ACBM), as well as lead-based paint (LBP). The scope of this inspection included:

- 1) Performing an ACBM and LBP building inspection which included:
 - Inspecting, identifying, and sampling suspect friable ACBM.
 - Inspecting and identifying suspect non-friable ACBM.
 - Inspecting and identifying building components suspected of being coated with LBP.
 - Documenting locations of asbestos and type of asbestos materials and lead-based painted building components on drawings.
 - Preparing a comprehensive report documenting the sampling procedures and results of the ACBM and LBP inspection.

1.2 QUALITY ASSURANCE AND QUALITY CONTROL

Quality Assurance and Quality Control (QA/QC) measures adopted by Maxim involved field and office components. Key parameters are summarized below:

1.2.1 Field QA/QC

- Review inspection forms for completeness;
- Check Homogeneous Materials Listing for sufficient number of collected samples;
- Verify locations of major mechanical components;
- Re-check three representative general areas for ACBM and LBP locations and quantities.

1.2.2 Office QA/QC

- Review lab results for completeness;
- Ensure appropriate cross-referencing of results with field forms for the identification of ACBM and LBP;
- Ensure drawings are updated as necessary following field QC;
- Verify approximate quantities of ACBM based on drawing review;
- Review recorded field comments for meaning, incorporate as necessary into report.

1.3 DRAWING DEVELOPMENT

The drawings provided in this report are based on field drawings that were prepared on site during the inspection phase. While performing the inspection, space designations were assigned to all discrete areas and recorded on the drawings. The locations of the ACM and LBP homogeneous areas were included after completion of the laboratory analysis of bulk samples. The final drawings were prepared using computer aided drafting software (Auto CAD).

2.0 ASBESTOS INSPECTION:

2.1 ASBESTOS OVERVIEW:

Asbestos is a trade name for a group of fibrous naturally occurring minerals which was used widely in building materials because of its ability to bind, resist chemicals, insulate, and fireproof. Exposure to elevated levels of asbestos fibers has been documented to cause a variety of diseases including asbestosis and cancer. Consequently, the application, removal, and disposal of asbestos-containing materials is regulated by several agencies. A summary of the regulations regarding asbestos-containing materials is presented in Appendix A.

One definition for asbestos containing building materials (ACBM) was taken from Environmental Protection Agency regulations (40 CFR, Part 763 - Asbestos Model Accreditation Plan and Section 202, Toxic Substance Control Act):

- 1) Friable asbestos-containing material is material containing more than one percent asbestos which has been applied to ceilings, walls, structural members, piping, duct work or any other part of a building, which when dry, may be crumbled, pulverized, or reduced to powder by hand pressure. The term includes non-friable, asbestos-containing materials after it becomes damaged, by any means, such that when dry, it may be crumbled, pulverized, or reduced to powder by hand-pressure. This definition also includes flooring materials which have become friable.

Another definition taken from Occupational Safety and Health Administration (OSHA) regulations (29 CFR Parts 1910 and 1926):

- 2) Asbestos-containing materials are defined as being any material which contains more than one percent asbestos and also defines certain high risk materials, which are presumed to contain asbestos, as Presumed Asbestos Containing Materials (PACM). The PACM designation applies to thermal system insulation, sprayed on or troweled on surfacing material and debris where such material is present. The PACM terminology was added to ensure compliance with the hazard communication provisions of the laws and specifically for buildings constructed prior to 1980.

2.2 PROCEDURES:

The asbestos inspection was performed using the applicable portions of the currently recognized standard protocol developed for schools under AHERA, as promulgated in Title 40, Code of Federal Regulations (40 CFR), Part 763 and as amended in the Federal Register. Since the primary concern for this investigation was to identify potential asbestos hazards in each of the designated housing units, Maxim representatives visually inspected existing conditions within each selected living unit.

2.2.1 Inspection and Sampling:

The inspection was conducted by our accredited inspectors, and consisted of a detailed visual survey of surfacing materials, thermal system insulation, and miscellaneous materials throughout each of the designated units. Suspect ACBM was then grouped into homogeneous materials and sampling plans developed. Components of the inspection included:

- Homogeneous suspect materials were identified. These are summarized for each individual building in our Findings Section 4.0. Areas from which samples were to be obtained were also identified during this task.
- Bulk samples of friable, or potentially friable, suspect materials were collected and analyzed to confirm whether or not the suspect materials contain asbestos.
- All suspect flooring and baseboard materials were assumed to contain asbestos per Maxim's proposal to Thomas, Dean and Hoskins dated August 30, 1999.
- An assessment was made of known or assumed ACBM, generally classifying the materials using categories defined in the National Emission Standards of Hazardous Air Pollutants (NESHAP), for asbestos. Further description of the NESHAP categories are presented in Section 2.2.3.

Homogeneous areas of suspect ACBM were, for the purposes of this study and as outlined in the AHERA sampling protocol, placed into the following four material categories types. AHERA sampling protocol specifies sampling procedures for each material type:

Friable Surfacing Material

- 1) At least three bulk samples from each homogeneous material that is 1,000 square feet or less.
- 2) At least five bulk samples from each homogeneous material that is greater than 1,000 square feet but less than or equal to 5,000 square feet.
- 3) At least seven bulk samples from each homogeneous material that is greater than 5,000 square feet.

Thermal System Insulation

- 1) In a randomly distributed manner, at least three bulk samples from each homogeneous material of thermal system insulation that is not assumed to contain asbestos.
- 2) At least one bulk sample from each homogeneous material of patched thermal system insulation that was not assumed to be asbestos-containing material (ACM).
- 3) In a manner sufficient to determine whether the material was ACM or not ACM, (generally three samples), bulk samples from each insulated mechanical system that was not assumed to be ACM where cement or plaster was used on fittings such as tees, elbows, or valves.
- 4) Bulk samples were not collected from any homogeneous material where the inspector determined that the thermal system insulation is fiberglass, foam glass, rubber, or other non-asbestos-containing building material.

Miscellaneous Material

- 1) In a manner sufficient to determine whether a material is an ACBM or not, three bulk samples were collected from each area of homogeneous friable miscellaneous material that was not assumed to be ACM.

Nonfriable Miscellaneous Material

- 1) If any nonfriable suspect homogeneous ACBM was not assumed to be an ACBM, then in a manner sufficient to determine whether the material is ACM or not, bulk samples were collected from the homogeneous material.

Sample locations for this survey were selected in a non-random fashion, with emphasis placed on obtaining samples of each type of accessible, suspect material and minimizing damage to the material being sampled. Samples were collected by carefully removing small portions of the suspect material in a non-abrasive manner. If possible, samples from existing damaged areas or loose pieces of material were collected. Immediately after collection, samples were placed in pre-labeled plastic containers. The containers were then placed in a large resealable plastic bag for transportation to the laboratory.

Samples were obtained by trained, accredited, experienced persons using techniques such as wet slicing, wet boring or similar methods designed to limit contamination of the area during sampling. As indicated the Statement of Work, destructive sampling was permitted, and Maxim did not, therefore, perform permanent repair of sampled materials.

2.2.2 Laboratory Analysis:

Bulk samples obtained during the inspection were assigned sample numbers and entered on sample summary sheets. The samples were shipped to Northern Analytical Laboratories, Inc., in Billings, Montana, for analysis. The analysis was performed in general accordance with EPA Interim Method 600/M4-82-020, which employs Polarized Light Microscopy (PLM) techniques with dispersion staining for identification of mineral forms of asbestos. The quantification of asbestos in the sample is intended to be an estimate only, and the limit of detection for this method is approximately 1% by volume. The results of the analysis are reported on the Sample Collection and Analysis Data Sheets.

It is a requirement under the Administrative Rules of Montana, Chapter 74, 17.74.307(h), that analysis for bulk samples is to be done by a laboratory approved by the National Institute of Standards Technology (NIST). Northern Analytical Laboratories, Inc. was assigned "accredited" status by the National Institute of Standards and Technology's National Voluntary Laboratory Accreditation Program (NVLAP), for bulk sample analysis on April 1, 1989.

2.2.3 NESHAP Categories:

Following receipt of the laboratory analysis, homogeneous ACBM were identified and the quantities determined. The materials were then categorized using NESHAP criteria for each ACBM.

The NESHAP Categories are defined as:

Category I are non-friable asbestos-containing packings, gaskets, resilient floor covering, and asphalt roofing products containing more than 1 percent asbestos.

Category II are non-friable ACBM excluding Category I non-friable ACBM, containing more than one percent asbestos.

Regulated Asbestos Containing Materials (RACM) are friable materials; Category I non-friable materials that will or may be subjected to sanding, grinding, cutting, or abrading; or Category II non-friable materials that have a high probability of becoming or has become crumbled, pulverized, or reduced to powder by forces expected to act on the material in the course of demolition or renovation operations.

3.0 LEAD-BASED PAINT INSPECTION

3.1 LEAD-BASED PAINT OVERVIEW

Lead-based paint is of concern both as a source of direct exposure through ingestion of paint chips and as a contributor to lead in interior dust and exterior soil. Regulatory agencies which have addressed lead-based paint include the Environmental Protection Agency (EPA), the Occupational Safety and Health Administration (OSHA), the Department of Housing and Urban Development (HUD), and the Consumer Products Safety Commission (CPSC). A review of these regulations is presented in Appendix A. A lead-based paint is defined as:

- 1) Paint in liquid form which contains 0.06%, by weight, calculated as lead metal in total nonvolatile content of the liquid paint, or
- 2) Paint already applied which tests equal to or greater than 0.5% by weight when using Atomic Absorption Spectroscopic analysis.
- 3) Paint already applied which tests equal to or greater than 1.0 milligram per square centimeter (mg/cm^2) when using field X-Ray Fluorescence (XRF) methodology.

3.2 PROCEDURES

Maxim used XRF sampling methodology as outlined in 24 CFR Part 35 (HUD), for determining lead concentrations in paint.

3.2.1 Inspection and Sampling

Certified Maxim inspection personnel conducted a detailed room-by-room inspection of the building, documenting types of painted building components, substrate materials and general paint colors. Typical building components include walls, floors, ceilings, doors, window units, baseboards, stairway components, radiator or cabinet type heat units, structural members, HVAC system components, and mechanical system components; and typical substrate materials include plaster, wood, drywall and metal. The painted building components were then grouped into Lead-Based Paint Homogeneous Areas (LHA's) based on specific component type and substrate material, and sampling plans were developed. The color of each homogeneous area was also documented.

3.2.2 XRF Sampling Methodology

Field X-Ray Fluorescence (XRF) is identified in 24 CFR Part 35 (HUD) as the recommended method to determine lead concentrations in paint. For this inspection, Maxim personnel utilized the *Niton XL* Spectrum Analyzer equipped with a computer program which automatically calculates measurable amounts of lead in paint by correcting for substrate conditions.

XRF results are classified using threshold values. The results are considered positive if they are greater than or equal to the threshold limit and negative if they are less than the threshold limit. Threshold limits of the *Niton XL* XRF equipment are 1.0 mg/cm^2 , $1.0 \pm 0.15 \text{ mg/cm}^2$, for surface lead, $1.0 \pm 0.2 \text{ mg/cm}^2$ for buried lead, and $1.0 \pm 0.3 \text{ mg/cm}^2$ for deeply buried lead, for all substrates at a 95% confidence interval. The depth index is explained as follows; 1.0 - 3.0 for surface lead; 3.1 - 5.0 for buried lead; and 5.1 - 10 for deeply buried lead. The *Niton XL* displays readings and ancillary information useful for classification purposes. Appendix F presents a summary of the results for the XRF readings.

3.2.3 Summary of Lead Based Paint

According to the HUD guidelines, paint is considered lead based if the concentration of lead in the paint is equal to or greater than 1.0 mg/cm^2 as measured by x-ray fluorescence or if it exceeds 5,000 milligrams per kilogram (mg/kg) or 0.5% by weight, as determined by laboratory analysis.

4.0 FINDINGS

A general summary of the designated properties inspected is as follows:

ADDRESS	APPROXIMATE SIZE, SF	ACBM IDENTIFIED	LBP IDENTIFIED
#11 Aspen Street	1950	Yes	Yes
#12 Aspen Street	1850	Yes	Yes
#2 Cedar Street.	2400	Yes	Yes
#12 Birch Street	1650	Yes	Yes

The housing units on Aspen, Cedar and Birch were constructed during 1960s. The units designated in the Capehart Family Housing Improvement Project have had renovation work done at various times. Each of the units inspected contained various types of flooring, such as tile or linoleum, which were installed at different times as occupancy changed. It is possible that there are multiple layers of flooring with concealed layers that were not identified since flooring samples were not collected. All resilient floor coverings were assumed to contain asbestos.

Due to the differences in building materials, the designated apartment units were inspected, sampled, and reported separately. Reference the ACBM and LBP Diagrams (Appendix D and Appendix G) for specific locations of identified materials.

4.1 CAPEHART FAMILY HOUSING UNITS:

The buildings located at #11 Aspen, #2 Cedar and #12 Birch are single-story wood frame buildings with basements and crawlspaces. The residence located at #12 Aspen is a two-story, wood frame building with a basement and crawlspace. All the units inspected have asphalt shingled roofs and metal siding. Interior finishes are generally wood, sheet vinyl, resilient tile or carpeted floors; sheetrock walls and ceilings. The heating system consists of individual natural gas fired, forced air furnace units located in the basement. Mechanical systems such as piping and ductwork is routed in the walls and is uninsulated. Attic spaces were not accessible in the units surveyed with the exception of the residence at #2 Cedar. The attic of this unit was insulated with a combination of blown in and rolled fiberglass insulation.

The units inspected were all painted on the interiors with white or cream paint on the walls, ceilings, doors and windows. The exteriors were finished with painted metal siding, wood and metal doors and painted wood windows.

4.2 HOUSING UNIT INSPECTION SUMMARY:

A summary of the homogeneous areas of asbestos containing building materials and lead-based paint found in each unit inspected are listed in the following tables:

4.2.1. #11 Aspen Street

#11 ASPEN STREET SUMMARY OF ASBESTOS CONTAINING MATERIALS				
Homogeneous Material No.	Homogeneous Material Description and Material Location	Quantity SF/LF/EA ¹	PERCENT ASBESTOS	NESHAP Category ²
F1.1	Yellow & Tan Linoleum and Mastic	135 SF	Assumed	Cat I
F1.2	Tile Pattern Linoleum and Mastic	35 SF	Assumed	Cat I
M1.1	Asphalt Roofing Materials	Not Quantified	Assumed	Cat I
M3.1	Wallboard & Taping Compound	3,040 SF	3%*	NA*
S1.1	Ceiling Surfacing Compound	920 SF	3%	RACM

¹ SF - Square feet; LF - Linear feet; EA - Each
² NESHAP Categories: I: Category I
 II: Category II
 RACM: Regulated Asbestos Containing Material

* Composite of wallboard and taping system sample is less than 1% asbestos - not regulated by State of Montana NESHAPs. Only OSHA worker exposure regulations apply.

All materials in the building suspected to be asbestos-containing were determined positive by laboratory analysis.

#11 ASPEN STREET SUMMARY OF LEAD-BASED PAINT			
Lead Homogeneous Area No.	Building Component and General Location	Lead Concentration mg/cm ²	Condition
14F	Exterior Green Wood Entry Doors	2.04	Solid
17F	Exterior Green Wood Door Jambs	1.19	Solid
23A	Exterior White Wood Windows - Upper & Lower Units	>5.09	Solid
26A	Interior White Wood Baseboards	1.77	Solid
59F	Exterior Green Wood Soffit and Beams	>5.09	Solid

mg/cm² = milligram per square centimeter

4.2.2 #12 Aspen Street

#12 ASPEN STREET SUMMARY OF ASBESTOS CONTAINING MATERIALS				
Homogeneous Material No.	Homogeneous Material Description and Material Location	Quantity SF/LF/EA ¹	PERCENT ASBESTOS	NESHAP Category ²
F1.1	Tan & Yellow Linoleum and Mastic	130 SF	Assumed	Cat I
F1.2	Orange Linoleum and Mastic	45 SF	Assumed	Cat I
M1.1	Asphalt Roofing Materials	Not Quantified	Assumed	Cat I
M3.1	Wallboard & Taping Compound	2,700 SF	3%*	NA*
M12.1	Mastic Under 4" Rubber Baseboard	2 LF	Assumed	Cat I
S1.1	Ceiling Surfacing Compound	980 SF	3%	RACM

¹ SF = Square feet; LF = Linear feet; EA = Each
² NESHAP Categories: I: Category I
 II: Category II
 RACM: Regulated Asbestos Containing Material
 * Composite of wallboard and taping system sample is less than 1% asbestos – not regulated by State of Montana NESHAPs. Only OSHA worker exposure regulations apply.

All materials in the building suspected to be asbestos-containing were determined positive by laboratory analysis.

#12 ASPEN STREET SUMMARY OF LEAD-BASED PAINT			
Lead Homogeneous Area No.	Building Component and General Location	Lead Concentration Mg/cm ²	Condition
14A	Exterior White Wood Entry Door	2.26	Solid
14B	Exterior Cream Wood Door	>5.09	Solid
17A	Exterior White Wood Door Jamb	2.62	Solid
23A	Exterior White Wood Window	2.92	Solid
26A	Interior White Wood Baseboard	2.05	Solid
33I	Exterior Black Metal Hand Rail	>5.09	Solid
46A	Exterior White Wood Soffit and Beams	>5.09	Solid

mg/cm² = milligrams per square centimeter

4.2.3 #2 Cedar Street

#2 CEDAR STREET SUMMARY OF ASBESTOS CONTAINING MATERIALS				
Homogeneous Material No.	Homogeneous Material Description and Material Location	Quantity SF/LF/EA ¹	PERCENT ASBESTOS	NESHAP Category ²
F1.1	Dark Yellow & Beige Pattern Linoleum and Mastic	110 SF	Assumed	Cat I
F1.2	Light Yellow & Beige Pattern Linoleum and Mastic	25 SF	Assumed	Cat I
F1.3	Beige Linoleum and Mastic	80 SF	Assumed	Cat I
F3.1	9" x 9" Tan & Gray Floor Tile and Mastic	400 SF	Assumed	Cat I
M1.1	Asphalt Roofing Materials	Not Quantified	Assumed	Cat I
M3.1	Wallboard & Taping Compound	3,500 SF	3%*	NA*
M12.1	Mastic Under 4" Rubber Baseboard	80 LF	Assumed	Cat I
S1.1	Ceiling Surfacing Compound	850 SF	3%	RACM
<p>¹ SF = Square feet; LF = Linear feet; EA = Each</p> <p>² NESHAP Categories: I: Category I II: Category II RACM: Regulated Asbestos Containing Material</p> <p>* Composite of wallboard and taping system sample is less than 1% asbestos -- not regulated by State of Montana NESHAPs. Only OSHA worker exposure regulations apply.</p>				

All materials in the building suspected to be asbestos-containing were determined positive by laboratory analysis.

#2 CEDAR STREET SUMMARY OF LEAD-BASED PAINT			
Lead Homogeneous Area No.	Building Component and General Location	Lead Concentration mg/cm ²	Condition
14C	Exterior Cream Wood Entry Door	2.37	Solid
17D	Exterior Brown Wood Door Jamb	2.01	Solid
17A	Exterior White Wood Door Jamb	1.02	Solid
20A	Interior White Wood Door Case	0.93	Solid
23A	Interior White Wood Basement Window	1.5	Solid
23D	Exterior Brown Wood Window	>5.09	Solid
26A	Interior White Wood Baseboard	1.22	Solid
33I	Exterior Black Metal Hand Rail	>5.09	Solid
55C	Exterior Tan Wood Soffit and Beams	>5.09	Solid
57A	Interior Metal Portion of Crawl Space Hatch	>5.09	Solid
mg/cm ² = milligrams per square centimeter			

4.2.4 #12 Birch Street

#12 BIRCH STREET SUMMARY OF ASBESTOS CONTAINING MATERIALS				
Homogeneous Material No.	Homogeneous Material Description and Material Location	Quantity SF/LF/EA ¹	PERCENT ASBESTOS	NESHAP Category ²
F1.1	Beige Linoleum and Mastic	180 SF	Assumed	Cat I
F1.2	Beige & Gray Linoleum and Mastic	80 SF	Assumed	Cat I
M1.1	Asphalt Roofing Materials	Not Quantified	Assumed	Cat I
M3.1	Wallboard & Taping Compound	2,950 SF	3%*	NA*
M12.1	Mastic Under 4" Rubber Baseboard	20 LF	Assumed	Cat I
S1.1	Ceiling Surfacing Compound	750 SF	3%	RACM

¹ SF = Square feet; LF = Linear feet; EA = Each
² NESHAP Categories: I: Category I
 II: Category II
 RACM: Regulated Asbestos Containing Material

* Composite of wallboard and taping system sample is less than 1% asbestos – not regulated by State of Montana NESHAPs. Only OSHA worker exposure regulations apply.

One additional material in the unit was suspected to contain asbestos. The material below was sampled and found not to contain asbestos.

- Wallboard and Taping Materials – Basement Level (M3.2)

#12 BIRCH STREET SUMMARY OF LEAD-BASED PAINT			
Lead Homogeneous Area No.	Building Component and General Location	Lead Concentration Mg/cm ²	Condition
14A	Exterior White Wood Entry Door	2.73	Solid
17A	Exterior White Wood Door Frame	3.31	Solid
17D	Exterior Brown Wood Door Jamb – Concealed by Metal (Understated Lead Concentration)	>0.65	Solid
23A	Interior White Wood Window	1.03	Solid
23D	Exterior Brown Wood Window	2.67	Solid
23F	Interior Green Wood Window	1.05	Solid
26A	Interior White Wood Baseboard	1.46	Solid
33I	Exterior Black Metal Hand Rail	>5.09	Solid
55C	Exterior Cream Wood Soffit and Beams	>5.09	Solid

mg/cm² = milligrams per square centimeter

5.0 LIMITATIONS

5.1 ASBESTOS

This asbestos inspection report was prepared based on information obtained during two site visits, and interpretation of the laboratory results of bulk samples of building materials collected during these site visits. The conclusions of this report are professional opinions based solely upon visual site observations and interpretations of chemical analyses as described in our report.

This report has been prepared to provide information concerning the various types and estimated quantities of asbestos-containing materials which may be present in the structures at this site. It includes only those materials that were visible and accessible at the time of our inspection. We did not remove any permanent building enclosures or disassemble any equipment to determine if any asbestos-containing materials were present. No samples were collected if the mechanical integrity of the material would be compromised. As a result, additional asbestos-containing materials may be present in inaccessible areas (e.g., between walls, beneath floors, etc.) of the buildings. Permanent building enclosures were not opened or disassembled for inspection, and additional asbestos-containing materials may also be present in these areas.

This inspection and report is intended to identify and assess asbestos-containing materials. It is not intended to be used by a contractor for removing asbestos-containing materials. Our opinions are intended exclusively for use by Thomas, Dean & Hoskins. The scope of services performed by Maxim may not be appropriate to satisfy the needs of other users, and any use or re-use of this document or the findings presented herein is at the sole risk of the user.

The sheetrock walls and ceilings in several of the units were classified as asbestos-containing material. OSHA does not recognize joint compound on wall board systems as an integral part of the wallboard. Therefore, any layer that contains asbestos is considered a separate material even if it is not separable from an associated material, such as joint compound on sheetrock. The EPA, however, regards multi-layered wall systems differently from OSHA per the January 5, 1994, August 15, 1994, and December 19, 1995 Asbestos NESHAP Clarification Regarding Analysis of Multi-layered Systems. The 1995 clarification states "that all multi-layered systems *except* for wall systems where joint compound was used only at the joints and nail holes must be analyzed as separate materials and results were not allowed to be combined to determine average asbestos content," whereas the January 5, 1994, clarification states, "When joint compound and/or tape is applied to wallboard it becomes an integral part of the wallboard and in effect becomes one material forming a wall system, Therefore, where demolition or renovation impacts such a wall system, a composite analysis of the wall system (percent of asbestos in the joint compound, tape and wallboard) should be conducted."

5.2 LEAD-BASED PAINT

Because it was not possible to sample or test every building surface and because multiple layers of paint may be present on any building component, additional lead-containing building materials may be present in the building. Further, changes in paint color schemes and previous renovation activities may have obscured existing lead-based paint such that this survey was unable to completely identify or assess the extent of the lead-based paint. It should also be noted that additional lead materials including vent line wrapping, waste line joint sealant, and radioactive material or room shielding may be present in the building but were outside the scope of this survey. These additional materials may also be present in inaccessible areas of the building.

This inspection and report is intended to identify and assess lead-based paint as defined by the Department of Housing and Urban Development (HUD). It is not intended to be used by a contractor for removing lead-based paint.

Our opinions are intended exclusively for use by Thomas, Dean & Hoskins. The scope of services performed by Maxim may not be appropriate to satisfy the needs of other users, and any use or re-use of this document, or the findings presented herein is at the sole risk of the user.

The opinions presented herein apply to the site conditions existing at the time of our investigation. Therefore, our opinions and recommendations may not apply to future conditions that may exist at the site, which we have not had the opportunity to evaluate.

This page intentionally blank

APPENDIX A

REGULATORY REVIEW
ASBESTOS AND LEAD-BASED PAINTED
BUILDING COMPONENTS

REGULATORY OVERVIEW

ASBESTOS

There are three federal agencies that regulate removal, transportation, and disposal of asbestos. They are the Environmental Protection Agency (EPA), the Occupational Safety and Health Administration (OSHA), and the Department of Transportation (DOT).

Environmental Protection Agency

The Environmental Protection Agency (EPA) was required under The Clean Air Act, to protect the general public from exposure to airborne contaminants that are known to be hazardous to human health. To meet this requirement, the EPA established National Emission Standards for Hazardous Air Pollutants (NESHAP). Asbestos was one of the first hazardous air pollutants regulated.

The asbestos NESHAP regulations protect the public by minimizing the release of asbestos fibers involving the processing, handling, and disposal of asbestos-containing material. To this end, NESHAP specified work practices to be followed during demolition and renovations of all structures, installations, and buildings (excluding residential buildings that have four or fewer dwelling units). The regulations also require notification to applicable state and local agencies and/or the EPA Regional Officer prior to all demolition or before renovations of buildings that contain a certain threshold amount of asbestos. The NESHAP has grouped asbestos-containing building material (ACBM) into three categories: Regulated Asbestos Containing Material, Category I non-friable ACBM, and Category II non-friable ACBM.

A regulated asbestos-containing material (RACM) means any friable asbestos material, a Category I non-friable that will or has been subjected to sanding, grinding, cutting, or abrading, or a Category II non-friable ACBM that has a high probability of becoming or has become crumbled, pulverized, or reduced to powder by forces expected to act in the material in the course of demolition or renovation operations.

A RACM is a friable asbestos-containing material or any Category I or Category II material that has become friable.

A Category I, non-friable asbestos-containing material is asbestos-containing packings, gaskets, resilient floor covering, and asphalt roofing products containing more than 1 percent asbestos.

Category II, non-friable ACBM means any material excluding Category I non-friable ACBM, containing more than 1 percent asbestos.

Occupational Safety and Health Administration

The Occupational Safety and Health Administration (OSHA) regulates asbestos exposure to workers under the Construction Industry Standard (29 CFR 1910.1101). This section regulates asbestos exposure in all work which includes demolition or salvage of structures where asbestos is present, removal or encapsulation of materials containing asbestos, construction, alteration, repair, maintenance or renovation of structures, substrates or portions that contain asbestos, installation of products that contain asbestos, asbestos spills/emergency cleanup and the transportation, disposal, storage, containment of and housekeeping activities involving asbestos or products containing asbestos, on the site or location at which construction activities are performed. This regulations sets minimum levels of work effort that must be performed on a given type of asbestos material.

OSHA defines these work types as Class I through IV. Class I means activities involving the removal of thermal system insulation or surfacing materials, Class II means activities involving the removal of asbestos-containing wallboard, floor tile and sheet flooring, roofing and siding shingles and construction mastics. Class III means repair and maintenance operations where ACM is likely to be disturbed, and Class IV means maintenance and custodial activities during which employees contact ACM and activities to clean up waste and debris containing ACM.

Department of Transportation

The Department of Transportation (DOT) requires that each individual bag of asbestos-containing waste be labeled and that the transport vehicle be properly placarded.

Waste Disposal

All asbestos-containing waste must be double wrapped, and properly labeled as required by OSHA, EPA and DOT. These wastes must be deposited in a Class II landfill approved by the EPA. NESHAP requires that no visible emissions to the outside air be allowed during collection, packaging, transportation or deposition of the ACM waste. The transportation and disposal of ACM waste is documented on a Waste Shipment Record. The transport of the waste must be performed by a person trained in the handling of asbestos, with a minimum of an EPA accredited 32-Hour Worker training class.

LEAD-BASED PAINT

Regulatory agencies which have addressed lead-based paint include EPA, Occupational Safety and Health Administration (OSHA), Department of Housing and Urban Development (HUD), and the Consumer Products Safety Commission (CPSC). Lead-Based Paint (LBP) in the liquid form is defined as any paint that contains more than six one hundredths of one percent (0.06) lead by weight, calculated as lead metal, in nonvolatile content of the liquid paint. For paint that has been applied, the Department of Housing and Urban Development (HUD) has defined LBP as any paint which tests equal to or greater than 1.0 mg/cm² when using Field X-Ray Fluorescence (XRF) or equal to greater than 0.5% by weight when using Flame Atomic Absorption spectrometry (FAAS) or Inductively Coupled Plasma Atomic Emission Spectrometry (ICP-AES) analysis.

However, the OSHA Standard for Lead in the Construction Industry does not recognize a minimum concentration of lead. Consequently, all painted surfaces, in which any detectable level of lead is present, must be considered as having the potential to present an occupational exposure to lead to an employee engaged in OSHA regulated construction work.

Occupational Safety and Health Administration

The OSHA Standard for Lead in the Construction Industry (29 CFR 1926.62) became effective June 3, 1993, and applies to all construction work where an employee may be occupationally exposed to lead. OSHA regulated construction work is defined as work for construction, alteration and/or repair, including painting and decorating. Typical activities that fall into these categories include: demolition or salvage of structures where lead or material containing lead are present, removal or encapsulation of materials containing lead, lead contamination/emergency cleanup, transportation, disposal, storage, or containment of lead or materials containing lead on the site or location at which construction activities are performed and maintenance operations associated with the construction activities described above.

HUD Guidelines

When it is determined that paint abatement and/or interim control activities will be performed on housing components, they should be performed according to practices that are described HUD Guidelines and the regulations promulgated under section 402 of TSCA, 15 USC 2682 (as appropriate for the unit in question), including clearance testing.

Waste Disposal Issues

Lead is considered toxic, and therefore is hazardous. However, lead-based paint may not be classified as hazardous. The first step in disposal of a waste that is suspected to be hazardous is representative testing. This is done by segregating the debris by type and assumed hazardous or nonhazardous. At the completion of the project, each waste is tested by the Toxicity Characteristic Leaching Procedure (TCLP). This is done to determine if the waste is "construction debris" or "hazardous waste". The disposal costs for non-hazardous waste are considerably less than that for debris that is considered hazardous, and it can be deposited in a municipal landfill. Debris that is considered hazardous, based on TCLP results, must be disposed of as hazardous waste, in accordance with the regulations promulgated under the Resource Conservation and Recovery Act (RCRA).

APPENDIX B

MAXIM PERSONNEL AHERA LEAD INSPECTOR
CERTIFICATES

Maxim
Technologies, Inc.

CERTIFICATE OF SATISFACTORY COMPLETION

Certificate No.: 990928-04

Expiration Date: September 28, 2000

Student Name: PETER KLEVBERG

(This individual has completed the requisite training for asbestos accreditation under TSCA Title II)

Street: 313 1/2 Central Avenue

City: Great Falls State: MT Zip: 59401

NAME OF COURSE: Asbestos Inspector Refresher/4-Hour

COURSE DATE: September 28, 1999 EXAMINATION DATE: N/A

EXAMINATION PERFORMANCE: PASS N/A FAIL N/A

COURSE APPROVAL:

AIR QUALITY DIVISION
MONTANA DEPARTMENT OF HEALTH
AND ENVIRONMENTAL SCIENCES
P O BOX 200901
HELENA MT 59620-0901
AND
U.S. EPA

COURSE PROVIDER:

MAXIM TECHNOLOGIES, INC.
600 SOUTH 25TH STREET
BILLINGS, MONTANA 59101
PHONE: (406) 248-9161

INSTRUCTOR: Rog. Herman, Jr.
Roger W. Herman, Jr.

Environmental Training Institute

University of North Dakota
Box 9031, Grand Forks, ND 58202
(701) 777-3341

hereby certifies that

Peter Klevberg

Maxim Technologies, Inc.
303 1/2 Central Ave.
Great Falls, MT 59401

has attended and successfully completed the

**Lead Hazard Reduction
Initial Training
for
Inspectors**

EPA Accredited Pursuant to
Section 402 of the Toxic Substances Control Act (TSCA) (15C.2582)


August 23-25, 1999

Course Location: Helena, MT

Exam Date: August 25, 1999

Certification No: LI-00010-0825

Expiration Date: February 25, 2000



Environmental Training Institute



Environmental Training Institute

University of North Dakota
Box 9031, Grand Forks, ND 58202
(701) 777-3341

hereby certifies that

Peter Klevberg

Maxim Technologies, Inc.
303 1/2 Central Ave.
Great Falls, MT 59401


has attended and successfully completed the

**Lead Hazard Reduction
Initial Training
for
Risk Assessors**

EPA Accredited Pursuant to
Section 402 of the Toxic Substances Control Act (TSCA) (15C.2582)

August 26-27, 1999

Course Location: Helena, MT
Exam Date: August 27, 1999
Certification No: LR-00010-0827
Expiration Date: February 27, 2000



Environmental Training Institute


NITON

CORPORATION

Certificate of Achievement

*Peter Klevberg
Maxim Technologies*

*has successfully completed the Manufacturer's Training Course for the
NITON Spectrum Analyzer and is now certified
in radiation safety and monitoring, measurement technology,
and machine maintenance of the NITON XRF Spectrum Analyzer.
(CIH's - The ABIH awards 1 CM point, approval #5827)*



99090262993
Certificate Number
06/28/99 Billings, MT
Date & Site of Course

Victoria Goygwinck

Training Coordinator
Kathleen R. Spots

Director of Training

Maxim
Technologies, Inc.

CERTIFICATE OF SATISFACTORY COMPLETION

Certificate No.: 990928-01

Expiration Date: September 28, 2000

Student Name: RICHARD LEFERINK

(This individual has completed the requisite training for asbestos accreditation under TSCA Title II)

Street: 303 Irene Street

City: Helena

State: MT

Zip: 59601

NAME OF
COURSE:

Asbestos Inspector Refresher / 4-Hour

COURSE
DATE:

September 28, 1999

EXAMINATION DATE:

N/A

EXAMINATION PERFORMANCE:

PASS N/A

FAIL

N/A

COURSE APPROVAL:

AIR QUALITY DIVISION
MONTANA DEPARTMENT OF HEALTH
AND ENVIRONMENTAL SCIENCES
P O BOX 200901
HELENA MT 59620-0901
AND
U.S. EPA

COURSE PROVIDER:

MAXIM TECHNOLOGIES, INC.
600 SOUTH 25TH STREET
BILLINGS, MONTANA 59101
PHONE: (406) 248-9161

INSTRUCTOR:

Roger W. Herman, Jr.
Roger W. Herman, Jr.

Environmental Training Institute

University of North Dakota
Box 9031, Grand Forks, ND 58202
(701) 777-3341

hereby certifies that

Richard Leferink

Maxim Technologies, Inc.
303 Irene Street
Helena, MT 59601


has attended and successfully completed the

**Lead Hazard Reduction
Refresher Training
for
Inspectors**

EPA Accredited Pursuant to
Section 402 of the Toxic Substances Control Act (TSCA) (15C.2582)

August 28, 1999

Course Location: Helena, MT
Exam Date: August 28, 1999
Certification No: LI-00003R-0828
Expiration Date: February 28, 2000


Environmental Training Institute

Environmental Training Institute

University of North Dakota
Box 9031, Grand Forks, ND 58202
(701) 777-3341

hereby certifies that

Richard Leferink

Maxim Technologies, Inc.
303 Irene Street
Helena, MT 59601

has attended and successfully completed the

**Lead Hazard Reduction
Refresher Training
for
Risk Assessors**

EPA Accredited Pursuant to
Section 402 of the Toxic Substances Control Act (TSCA) (15C.2582)


August 21, 1999

Course Location: Butte, MT

Exam Date: August 21, 1999

Certification No: RA-00004R-0821

Expiration Date: February 21, 2000



Environmental Training Institute



Certificate of Achievement


This is to certify that


Richard Leferink
Maxim Technology

*has successfully completed the Manufacturer's Training Course
for the NITON Spectrum Analyzer.*

*The one-day course covered radiation safety and monitoring,
measurement technology, and machine maintenance of all
NITON XRF machines.*

V961002-010
Certificate Number
10/02/96 - Portland, OR
Course Date & Site




Director of Training

President & CEO - NITON

This page intentionally blank

APPENDIX C

ACBM BULK SAMPLE
LABORATORY RESULTS

NORTHERN
Analytical Laboratories, Inc.

602 South 25th Street
P O Box 30315
Billings, MT 59107
Telephone: (406) 254-7226
Fax: (406) 254-1389

REPORT TO: ATTN: RICHARD LEFERINK
MAXIM TECHNOLOGIES, INC.
P O BOX 4699
HELENA MT 59604

DATE: October 20, 1999
JOB NUMBER: 87-911
SHEET: 1 of 3
INVOICE NO.: 25516345

REPORT OF: Building Material Analysis - Thomas, Dean & Hoskins - Capehart Family Housing #3
#11 Aspen Street - 9900589.100

CASE NARRATIVE:

On October 14, 1999, our laboratory received six building material samples from Richard Leferink. A completed chain of custody record was received which identified the above referenced project as the source of the samples. Our laboratory assigned laboratory numbers 141049 through 141054 to the samples. This analysis was performed using an Olympus BH-2 polarizing microscope at magnifications of 40X to 400X in general accordance with EPA Method 600/R-93/116, July 1993, which employs polarized light microscopic techniques with dispersion staining for identification of mineral forms of asbestos.

There are currently six types of mineral fiber that are regulated as asbestos minerals. These are divided into two categories: serpentine asbestos and amphibole asbestos. Serpentine asbestos is called chrysotile, which is the most commonly encountered type of asbestos in the United States. Five of the asbestos minerals are amphiboles. Included in this group are fibrous grunerite (amosite), fibrous riebeckite (crocidolite), fibrous anthophyllite, fibrous tremolite and fibrous actinolite.

The EPA test method for bulk analysis (EPA/600/R-93/116) states in paragraph 2.2.2, that "the detection limit for visual estimation is a function of the quantity of sample analyzed, the nature of matrix interference, sample preparation, and fiber size and distribution. Asbestos may be detected in concentrations of less than one percent by area if sufficient material is analyzed. Samples may contain fibers too small to be resolved by PLM (<0.25 micrometers in diameter) so detection of those fibers by this method may not be possible".

In the case of nonhomogeneous samples (samples which contain more than one visually distinct material which is not mixed), concentrations of materials are given for each layer and composite values are given for the entire sample. The quantification of asbestos in the sample is intended to be a volume estimate only. The concentrations of various components reported for these samples are intended to represent the materials received at our laboratory for testing only. Variations in the concentrations due to the limitations of the test method, equipment, and operator are given below.

- 1 - 10%, true concentrations may vary $\pm 5\%$ from the reported value
- 10 - 50%, true concentrations may vary $\pm 10\%$ from the reported value
- 50 - 100%, true concentrations may vary $\pm 10\%$ from the reported value

According to the National Emission Standards for Hazardous Air Pollutants; Asbestos NESHAP Revision Final Rule in the Federal Register, Volume 55, Number 224 dated November 20, 1990, any friable material containing less than 10 percent asbestos by the Polarized Light Microscopy (PLM) Method is recommended to be verified by the Point Count Method using PLM. Friable asbestos material means any material containing more than one percent asbestos as determined by the visual PLM method, that when dry can be crumbled, pulverized or reduced to powder with hand pressure. This rule applies to building renovations and demolitions.

As a mutual protection to clients, the public and ourselves, all reports are submitted as the confidential property of our clients and authorization for publication of statements, conclusions or extracts from or regarding our reports is reserved pending our written approval. Test results apply specifically to the samples tested only. The entire report shall not be reproduced, except in full, without the written approval of the laboratory. Samples will be disposed of after testing is completed unless other arrangements are agreed to in writing.

Building Material Analysis
Thomas, Dean & Hoskins - Capehart Family Housing #3
#11 Aspen Street - 9900589.100

October 20, 1999
Job No. 87-911
Sheet 2 of 3

The U.S. EPA Clarification of the Asbestos NESHAP Requirement to perform Point Counting dated May 8, 1991 states:

- ◆ First, that a sample which contains no asbestos by visual PLM does not have to be point counted.
- ◆ Second, the owner or operator of the building may choose to assume the asbestos amount to be greater than one percent and treat the material as asbestos containing material (ACM) or require point counting for verification.
- ◆ Third, if a result obtained by point counting is different from a result obtained by visual estimation, the point count result will be used.

We will hold the samples for sixty (60) days in the event you choose to have future analysis performed on any sample containing less than 10 percent asbestos.

The results are shown on the following page. A < sign indicates the value reported was the practical quantitation limit for these samples using the method described. Concentrations of analyte, if present, below this were not quantifiable.

On April 1, 1989, our laboratory was assigned "accredited" status by the National Institute of Standards and Technology's National Voluntary Laboratory Accreditation Program, (NVLAP), Laboratory Code No. 101292-0.

This report may not be used to claim a product endorsement by NVLAP or any agency of the U.S. government.

Analyzed by:

Mike Otness

Reviewed by:

[Signature]

Attachments: Chain of Custody
Sample Receipt Checklist

caj



**BUILDING MATERIAL ANALYSIS
ASBESTOS CONTENT**

**THOMAS, DEAN & HOSKINS - CAPEHART FAMILY HOUSING #3
#11 ASPEN STREET - 9900589.100**

October 20, 1999
Job No. 87-911
Sheet 3 of 3

Lab No.	Sample Identification	Sample Description	Asbestos Identification and Estimated Quantity	Non-Asbestos Fibrous Material Identification and Estimated Quantity
141049	3.1A-Wallboard & joint compound - Rm 105	Three layers: 1) White crystalline layers w/paint (3%) 2) White/tan fibrous layers (20%) 3) White chalky solid (77%) Composite of Layers:	3% Chrysotile None Detected None Detected <1% Chrysotile	97% Nonfibrous Binder 90% Cellulose 10% Nonfibrous Binder <1% Cellulose 99% Nonfibrous Binder
141050	M3.1B-Wallboard & joint compound - Rm 103	Three layers: 1) Off-white crystalline layer (40%) 2) Tan fibrous backing (20%) 3) White chalky solid (40%) Composite of Layers:	3% Chrysotile None Detected None Detected 1% Chrysotile	97% Nonfibrous Binder 90% Cellulose 10% Nonfibrous Binder <1% Cellulose 99% Nonfibrous Binder
141051	M3.1C-Wallboard & joint compound-Rm 104	Three layers: 1) Off-white crystalline solid w/paint (95%) 2) Tan fibrous backing (2%) 3) White chalky solid (3%) Composite of Layers:	3% Chrysotile None Detected None Detected 3% Chrysotile	97% Nonfibrous Binder 90% Cellulose 10% Nonfibrous Binder <1% Cellulose 99% Nonfibrous Binder
141052	S1.1A-Surfacing compound Rm 104	One layer: 1) White crystalline layer w/paint (100%)	None Detected	100% Nonfibrous Binder
141053	S1.1B-Surfacing compound Rm 110	One layer: 1) Gray crystalline layer w/paint (100%)	3% Chrysotile	97% Nonfibrous Binder
141054	S1.1C-Surfacing compound Rm 109	Three layers: 1) White crystalline layer w/paint (30%) 2) Tan fibrous backing (40%) 3) White chalky solid (30%) Composite of Layers:	3% Chrysotile None Detected None Detected <1% Chrysotile	97% Nonfibrous Binder 90% Cellulose 10% Nonfibrous Binder <1% Cellulose 99% Nonfibrous Binder



SAMPLE RECEIPT CHECKLIST

Dear Valued Client: This checklist documents the condition of your sample(s) as it (they) arrived at our lab. Please review it and familiarize yourself with its contents. Should you have any questions or comments, please contact us. Thank you for your use of our services.

Client Name M. Helman Date/Time Received 10/14/99 0730
 Project Thomas Doan: Helman Received by MW
 Laboratory Number(s) 140988/993 Carrier Name USPS
 Checklist Completed by MW 10/14/99 Sample Type PLM
Initials / Date

	YES	NO		YES	NO
1. Shipping container in good condition?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	14. pH check performed by: _____		
2. Custody seals present on shipping container? Condition: Intact <input checked="" type="checkbox"/> Broken <input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	15. Metals bottle(s) pH <2?	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Chain of custody present?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	16. Nutrient bottle(s) pH <2?	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4. Chain of custody signed when relinquished and received?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	17. Cyanide bottle(s) pH >12?	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. Chain of custody agrees with sample labels?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	18. Sulfide bottle(s) pH >9?	<input checked="" type="checkbox"/>	<input type="checkbox"/>
6. Custody seals on sample bottles? Condition: Intact <input type="checkbox"/> Broken <input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	19. TOC bottle(s) pH <2?	<input checked="" type="checkbox"/>	<input type="checkbox"/>
7. Samples in proper container/bottle?*	<input checked="" type="checkbox"/>	<input type="checkbox"/>	20. Phenolics bottle(s) pH <2?	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. Sample containers intact?*	<input checked="" type="checkbox"/>	<input type="checkbox"/>	21. Oil & grease bottle(s) pH <2? (checked by analyst)	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. Sufficient sample volume for indicated test?*	<input checked="" type="checkbox"/>	<input type="checkbox"/>	22. DRO/418.1 bottle(s) pH <2? (checked by analyst)	<input checked="" type="checkbox"/>	<input type="checkbox"/>
10. Ice/Frozen Blue Ice present in shipping container? (circle one) container temperature 1. <input type="checkbox"/> 2. <input type="checkbox"/> 3. <input type="checkbox"/> * (if <0 or >10)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	23. Volatiles (VOA) pH <2? (VOA pH checked by analyst)	<input checked="" type="checkbox"/>	<input type="checkbox"/>
11. All samples rec'd within holding time?*	<input checked="" type="checkbox"/>	<input type="checkbox"/>	24. Herbicides (515) pH <2? (checked by analyst)	<input checked="" type="checkbox"/>	<input type="checkbox"/>
12. VOA vials have zero headspace? * (if contains >5mm headspace)	<input type="checkbox"/>	<input checked="" type="checkbox"/>	25. Semivolatiles (525) pH <2? (checked by analyst)	<input checked="" type="checkbox"/>	<input type="checkbox"/>
13. Trip Blank received?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	26. Client contacted?	<input checked="" type="checkbox"/>	<input type="checkbox"/>
			27. Person contacted	<input checked="" type="checkbox"/>	<input type="checkbox"/>
			28. Date contacted	<input checked="" type="checkbox"/>	<input type="checkbox"/>

NOTES: Samples may be affected when not transported at the temperature recommended by the EPA for the test you've selected. Please contact the lab if you have concerns about the temperature of your samples.

* Critical item - if marked "NO" contact lab manager.

COMMENTS: _____

NORTHERN
Analytical Laboratories, Inc.

602 South 25th Street
P O Box 30315
Billings, MT 59107
Telephone: (406) 254-7226
Fax: (406) 264-1389

REPORT TO: ATTN: RICHARD LEFERINK
MAXIM TECHNOLOGIES, INC.
P O BOX 4699
HELENA MT 59604

DATE: October 20, 1999
JOB NUMBER: 87-911
SHEET: 1 of 3
INVOICE NO.: 25516347

REPORT OF: Building Material Analysis - Thomas, Dean & Hoskins - Capehart Family Housing #3
#12 Aspen - 9900589.100

CASE NARRATIVE:

On October 14, 1999, our laboratory received six building material samples from Richard Leferink. A completed chain of custody record was received which identified the above referenced project as the source of the samples. Our laboratory assigned laboratory numbers 140988 through 140993 to the samples. This analysis was performed using an Olympus BH-2 polarizing microscope at magnifications of 40X to 400X in general accordance with EPA Method 600/R-93/116, July 1993, which employs polarized light microscopic techniques with dispersion staining for identification of mineral forms of asbestos.

There are currently six types of mineral fiber that are regulated as asbestos minerals. These are divided into two categories: serpentine asbestos and amphibole asbestos. Serpentine asbestos is called chrysotile, which is the most commonly encountered type of asbestos in the United States. Five of the asbestos minerals are amphiboles. Included in this group are fibrous grunerite (amosite), fibrous riebeckite (crocidolite), fibrous anthophyllite, fibrous tremolite and fibrous actinolite.

The EPA test method for bulk analysis (EPA/600/R-93/116) states in paragraph 2.2.2, that "the detection limit for visual estimation is a function of the quantity of sample analyzed, the nature of matrix interference, sample preparation, and fiber size and distribution. Asbestos may be detected in concentrations of less than one percent by area if sufficient material is analyzed. Samples may contain fibers too small to be resolved by PLM (<0.25 micrometers in diameter) so detection of those fibers by this method may not be possible".

In the case of nonhomogeneous samples (samples which contain more than one visually distinct material which is not mixed), concentrations of materials are given for each layer and composite values are given for the entire sample. The quantification of asbestos in the sample is intended to be a volume estimate only. The concentrations of various components reported for these samples are intended to represent the materials received at our laboratory for testing only. Variations in the concentrations due to the limitations of the test method, equipment, and operator are given below.

- 1 - 10%, true concentrations may vary $\pm 5\%$ from the reported value
- 10 - 50%, true concentrations may vary $\pm 10\%$ from the reported value
- 50 - 100%, true concentrations may vary $\pm 10\%$ from the reported value

According to the National Emission Standards for Hazardous Air Pollutants; Asbestos NESHAP Revision Final Rule in the Federal Register, Volume 55, Number 224 dated November 20, 1990, any friable material containing less than 10 percent asbestos by the Polarized Light Microscopy (PLM) Method is recommended to be verified by the Point Count Method using PLM. Friable asbestos material means any material containing more than one percent asbestos as determined by the visual PLM method, that when dry can be crumbled, pulverized or reduced to powder with hand pressure. This rule applies to building renovations and demolitions.

As a mutual protection to clients, the public and ourselves, all reports are submitted as the confidential property of our clients and authorization for publication of statements, conclusions or extracts from or regarding our reports is reserved pending our written approval. Test results apply specifically to the samples tested only. The entire report shall not be reproduced, except in full, without the written approval of the laboratory. Samples will be disposed of after testing is completed unless other arrangements are agreed to in writing.

Building Material Analysis
Thomas, Dean & Hoskins - Capehart Family Housing #3
#12 Aspen - 9900589, 100

October 20, 1999
Job No. 87-911
Sheet 2 of 3

The U.S. EPA Clarification of the Asbestos NESHAP Requirement to perform Point Counting dated May 8, 1991 states:

- ◆ First, that a sample which contains no asbestos by visual PLM does not have to be point counted.
- ◆ Second, the owner or operator of the building may choose to assume the asbestos amount to be greater than one percent and treat the material as asbestos containing material (ACM) or require point counting for verification.
- ◆ Third, if a result obtained by point counting is different from a result obtained by visual estimation, the point count result will be used.

We will hold the samples for sixty (60) days in the event you choose to have future analysis performed on any sample containing less than 10 percent asbestos.

The results are shown on the following page. A < sign indicates the value reported was the practical quantitation limit for these samples using the method described. Concentrations of analyte, if present, below this were not quantifiable.

On April 1, 1989, our laboratory was assigned "accredited" status by the National Institute of Standards and Technology's National Voluntary Laboratory Accreditation Program, (NVLAP), Laboratory Code No. 101292-0.

This report may not be used to claim a product endorsement by NVLAP or any agency of the U.S. government.

Analyzed by:

Mike O'neiss

Reviewed by:

Carleen A. H.

Attachments: Chain of Custody
Sample Receipt Checklist

caj

NORTHERN

Analytical Laboratories, Inc.

BUILDING MATERIAL ANALYSIS ASBESTOS CONTENT

THOMAS, DEAN & HOSKINS - CAPEHART FAMILY HOUSING #3
#12 ASPEN - 9900589.100

October 20, 1999
Job No. 87-911
Sheet 3 of 3

Lab No.	Sample Identification	Sample Description	Asbestos Identification and Estimated Quantity	Non-Asbestos Fibrous Material Identification and Estimated Quantity
140988	M3.1A-Wallboard & joint compound - Rm 201	Three layers: 1) White crystalline layer w/paint (5%) 2) Tan fibrous backing (25%) 3) White chalky solid (70%)	None Detected None Detected None Detected	100% Nonfibrous Binder & Paint 90% Cellulose 10% Nonfibrous Binder <1% Cellulose 99% Nonfibrous Binder
140989	M3.1B-Wallboard & joint compound - Rm 201	Five layers: 1) Off-white crystalline w/brown mastic (2%) 2) White crystalline layer w/paint (5%) 3) Tan fibrous backing (<1%) 4) White chalky solid (90%) 5) Brown fibrous mass w/wood chips (2%) Composite of Layers:	3% Chrysotile None Detected None Detected None Detected None Detected <1% Chrysotile	97% Nonfibrous Binder 100% Nonfibrous Binder 90% Cellulose 10% Nonfibrous Binder <1% Cellulose 99% Nonfibrous Binder 90% Cellulose 10% Nonfibrous Binder & Perlite
140990	M3.1C-Wallboard & joint compound - Rm 102	Two layers: 1) Off-white crystalline layer w/paint (60%) 2) Brown solid w/debris (40%) Composite of Layers:	2% Chrysotile None Detected 1% Chrysotile	98% Nonfibrous Binder 100% Nonfibrous Binder
140991	S1.1A-Surfacing compound Rm 101	Three layers: 1) Gray crystalline layer w/paint (30%) 2) Tan fibrous layer (45%) 3) White chalky solid (25%) Composite of Layers:	3% Chrysotile None Detected None Detected <1% Chrysotile	97% Nonfibrous Binder 90% Cellulose 10% Nonfibrous Binder <1% Cellulose 99% Nonfibrous Binder
140992	S1.1B-Surfacing compound Rm 101	One layer: 1) Gray crystalline layer w/paint (100%)	3% Chrysotile	97% Nonfibrous Binder
140993	S1.1C-Surfacing compound Rm 101		HOLD NOT ANALYZED	



SAMPLE RECEIPT CHECKLIST

Dear Valued Client: This checklist documents the condition of your sample(s) as it (they) arrived at our lab. Please review it and familiarize yourself with its contents. Should you have any questions or comments, please contact us. Thank you for your use of our services.

Client Name M-Helmer Date/Time Received 10/14/99 0730
Project Thomas, Dean; Helmer Received by MLW
Laboratory Number(s) 140988/993 Carrier Name USPS
Checklist Completed by MLW 10/14/99 Sample Type PLM

- 1. Shipping container in good condition? YES NO
2. Custody seals present on shipping container? YES NO
3. Chain of custody present? YES NO
4. Chain of custody signed when relinquished and received? YES NO
5. Chain of custody agrees with sample labels? YES NO
6. Custody seals on sample bottles? YES NO
7. Samples in proper container/bottle?* YES NO
8. Sample containers intact?* YES NO
9. Sufficient sample volume for indicated test?* YES NO
10. Ice/Frozen Blue Ice present in shipping container? (circle one) YES NO
11. All samples rec'd within holding time?* YES NO
12. VOA vials have zero headspace? YES NO
13. Trip Blank received? YES NO
14. pH check performed by: YES NO
15. Metals bottle(s) pH <2? YES NO
16. Nutrient bottle(s) pH <2? YES NO
17. Cyanide bottle(s) pH >12? YES NO
18. Sulfide bottle(s) pH >9? YES NO
19. TOC bottle(s) pH <2? YES NO
20. Phenolics bottle(s) pH <2? YES NO
21. Oil & grease bottle(s) pH <2? (checked by analyst) YES NO
22. DRO/418.1 bottle(s) pH <2? (checked by analyst) YES NO
23. Volatiles (VOA) pH <2? (VOA pH checked by analyst) YES NO
24. Herbicides (515) pH <2? (checked by analyst) YES NO
25. Semivolatiles (525) pH <2? (checked by analyst) YES NO
26. Client contacted? YES NO
27. Person contacted YES NO
28. Date contacted YES NO

NOTES: Samples may be affected when not transported at the temperature recommended by the EPA for the test you've selected. Please contact the lab if you have concerns about the temperature of your samples.

* Critical item - if marked "NO" contact lab manager.

COMMENTS:

NORTHERN

Analytical Laboratories, Inc

602 South 25th Street
P O Box 30315
Billings, MT 59107
Telephone: (406) 254-7228
Fax: (406) 254-1389

REPORT TO: ATTN: RICHARD LEFERINK
MAXIM TECHNOLOGIES, INC.
P O BOX 4699
HELENA MT 59604

DATE: October 20, 1999
JOB NUMBER: 87-911
SHEET: 1 of 3
INVOICE NO.: 25516348

REPORT OF: Building Material Analysis - Thomas, Dean & Hoskins - Capehart Family Housing #3
#2 Cedar Street - 9900589.100

CASE NARRATIVE:

On October 14, 1999, our laboratory received six building material samples from Richard Leferink. A completed chain of custody record was received which identified the above referenced project as the source of the samples. Our laboratory assigned laboratory numbers 140982 through 140987 to the samples. This analysis was performed using an Olympus BH-2 polarizing microscope at magnifications of 40X to 400X in general accordance with EPA Method 600/R-93/116, July 1993, which employs polarized light microscopic techniques with dispersion staining for identification of mineral forms of asbestos.

There are currently six types of mineral fiber that are regulated as asbestos minerals. These are divided into two categories: serpentine asbestos and amphibole asbestos. Serpentine asbestos is called chrysotile, which is the most commonly encountered type of asbestos in the United States. Five of the asbestos minerals are amphiboles. Included in this group are fibrous grunerite (amosite), fibrous riebeckite (crocidolite), fibrous anthophyllite, fibrous tremolite and fibrous actinolite.

The EPA test method for bulk analysis (EPA/600/R-93/116) states in paragraph 2.2.2. that "the detection limit for visual estimation is a function of the quantity of sample analyzed, the nature of matrix interference, sample preparation, and fiber size and distribution. Asbestos may be detected in concentrations of less than one percent by area if sufficient material is analyzed. Samples may contain fibers too small to be resolved by PLM (<0.25 micrometers in diameter) so detection of those fibers by this method may not be possible".

In the case of nonhomogeneous samples (samples which contain more than one visually distinct material which is not mixed), concentrations of materials are given for each layer and composite values are given for the entire sample. The quantification of asbestos in the sample is intended to be a volume estimate only. The concentrations of various components reported for these samples are intended to represent the materials received at our laboratory for testing only. Variations in the concentrations due to the limitations of the test method, equipment, and operator are given below.

- 1 - 10%, true concentrations may vary $\pm 5\%$ from the reported value
- 10 - 50%, true concentrations may vary $\pm 10\%$ from the reported value
- 50 - 100%, true concentrations may vary $\pm 10\%$ from the reported value

According to the National Emission Standards for Hazardous Air Pollutants, Asbestos NESHAP Revision Final Rule in the Federal Register, Volume 55, Number 224 dated November 20, 1990, any friable material containing less than 10 percent asbestos by the Polarized Light Microscopy (PLM) Method is recommended to be verified by the Point Count Method using PLM. Friable asbestos material means any material containing more than one percent asbestos as determined by the visual PLM method, that when dry can be crumbled, pulverized or reduced to powder with hand pressure. This rule applies to building renovations and demolitions.

As a mutual protection to clients, the public and ourselves, all reports are submitted as the confidential property of our clients and authorization for publication of statements, conclusions or extracts from or regarding our reports is reserved pending our written approval. Test results apply specifically to the samples tested only. The entire report shall not be reproduced, except in full, without the written approval of the laboratory. Samples will be disposed of after testing is completed unless other arrangements are agreed to in writing.

Building Material Analysis
Thomas, Dean & Hoskins - Capchart Family Housing #3
#2 Cedar Street - 9900589.100

October 20, 1999
Job No. 87-911
Sheet 2 of 3

The U.S. EPA Clarification of the Asbestos NESHAP Requirement to perform Point Counting dated May 8, 1991 states:

- ◆ First, that a sample which contains no asbestos by visual PLM does not have to be point counted.
- ◆ Second, the owner or operator of the building may choose to assume the asbestos amount to be greater than one percent and treat the material as asbestos containing material (ACM) or require point counting for verification.
- ◆ Third, if a result obtained by point counting is different from a result obtained by visual estimation, the point count result will be used.

We will hold the samples for sixty (60) days in the event you choose to have future analysis performed on any sample containing less than 10 percent asbestos.

The results are shown on the following page. A < sign indicates the value reported was the practical quantitation limit for these samples using the method described. Concentrations of analyte, if present, below this were not quantifiable.

On April 1, 1989, our laboratory was assigned "accredited" status by the National Institute of Standards and Technology's National Voluntary Laboratory Accreditation Program, (NVLAP), Laboratory Code No. 101292-0.

This report may not be used to claim a product endorsement by NVLAP or any agency of the U.S. government.

Analyzed by:

Mike O'Hess

Reviewed by:

Cathleen A. A.

Attachments: Chain of Custody
Sample Receipt Checklist

caj



**BUILDING MATERIAL ANALYSIS
ASBESTOS CONTENT**

**THOMAS, DEAN & HOSKINS -- CAPEHART FAMILY HOUSING #3
#2 CEDAR STREET - 9900589.100**

October 20, 1999
Job No. 87-911
Sheet 3 of 3

Lab No.	Sample Identification	Sample Description	Asbestos Identification and Estimated Quantity	Non-Asbestos Fibrous Material Identification and Estimated Quantity
140982	M3.1A-Wallboard & joint compound -- Rm 101	Three layers: 1) Gray crystalline layer w/paint (5%) 2) Tan fibrous backing (25%) 3) White chalky solid (70%) Composite of Layers:	3% Chrysotile None Detected None Detected <1% Chrysotile	97% Nonfibrous Binder 90% Cellulose 10% Nonfibrous Binder <1% Cellulose 99% Nonfibrous Binder
140983	M3.1B-Wallboard & joint compound - Rm 101	Three layers: 1) Gray crystalline layer w/paint (5%) 2) Tan fibrous backing (25%) 3) White chalky solid (70%) Composite of Layers:	3% Chrysotile None Detected None Detected <1% Chrysotile	97% Nonfibrous Binder 90% Cellulose 10% Nonfibrous Binder <1% Cellulose 99% Nonfibrous Binder
140984	M3.1C-Wallboard & joint compound -- Rm 106	Two layers: 1) Tan fibrous layer w/paint (15%) 2) White chalky solid (85%)	None Detected None Detected	90% Cellulose 10% Nonfibrous Binder <1% Cellulose 99% Nonfibrous Binder
140985	S1.1A-Surfacing compound Rm 103	One layer: 1) Gray crystalline layer w/paint (100%)	3% Chrysotile	97% Nonfibrous Binder
140986	S1.1B-Surfacing compound Rm 101		HOLD NOT ANALYZED	
140987	S1.1C-Surfacing compound Rm 106		HOLD NOT ANALYZED	



SAMPLE RECEIPT CHECKLIST

Dear Valued Client: This checklist documents the condition of your sample(s) as it (they) arrived at our lab. Please review it and familiarize yourself with its contents. Should you have any questions or comments, please contact us. Thank you for your use of our services.

Client Name M. Helmer Date/Time Received 10/14/99 0730
 Project Thomas, Dean & Harwin Received by MW
 Laboratory Number(s) 140988/993 Carrier Name USPS
 Checklist Completed by MW 10/14/99 Sample Type PLM
Initials / Date

	YES	NO		YES	NO
1. Shipping container in good condition?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	14. pH check performed by: _____		
2. Custody seals present on shipping container? Condition: Intact <input checked="" type="checkbox"/> Broken <input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	15. Metals bottle(s) pH <2?	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Chain of custody present?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	16. Nutrient bottle(s) pH <2?	<input type="checkbox"/>	<input type="checkbox"/>
4. Chain of custody signed when relinquished and received?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	17. Cyanide bottle(s) pH >12?	<input type="checkbox"/>	<input type="checkbox"/>
5. Chain of custody agrees with sample labels?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	18. Sulfide bottle(s) pH >9?	<input type="checkbox"/>	<input type="checkbox"/>
6. Custody seals on sample bottles? Condition: Intact <input type="checkbox"/> Broken <input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	19. TOC bottle(s) pH <2?	<input type="checkbox"/>	<input type="checkbox"/>
7. Samples in proper container/bottle?*	<input checked="" type="checkbox"/>	<input type="checkbox"/>	20. Phenolics bottle(s) pH <2?	<input type="checkbox"/>	<input type="checkbox"/>
8. Sample containers intact?*	<input checked="" type="checkbox"/>	<input type="checkbox"/>	21. Oil & grease bottle(s) pH <2? (checked by analyst)	<input type="checkbox"/>	<input type="checkbox"/>
9. Sufficient sample volume for indicated test?*	<input checked="" type="checkbox"/>	<input type="checkbox"/>	22. DRO/418.1 bottle(s) pH <2? (checked by analyst)	<input type="checkbox"/>	<input type="checkbox"/>
10. Ice/Frozen Blue Ice present in shipping container? (circle one) <u>NA</u> container temperature 1. _____ 2. _____ 3. _____ * (if <0 or >10)			23. Volatiles (VOA) pH <2? (VOA pH checked by analyst)	<input type="checkbox"/>	<input type="checkbox"/>
11. All samples rec'd within holding time?*	<input checked="" type="checkbox"/>	<input type="checkbox"/>	24. Herbicides (515) pH <2? (checked by analyst)	<input type="checkbox"/>	<input type="checkbox"/>
12. VOA vials have zero headspace? * (if contains >5mm headspace)	<input type="checkbox"/>	<input checked="" type="checkbox"/>	25. Semivolatiles (525) pH <2? (checked by analyst)	<input type="checkbox"/>	<input type="checkbox"/>
13. Trip Blank received?	<input type="checkbox"/>	<input type="checkbox"/>	26. Client contacted?	<input type="checkbox"/>	<input type="checkbox"/>
			27. Person contacted	<input type="checkbox"/>	<input type="checkbox"/>
			28. Date contacted	<input type="checkbox"/>	<input type="checkbox"/>

NOTES: Samples may be affected when not transported at the temperature recommended by the EPA for the test you've selected. Please contact the lab if you have concerns about the temperature of your samples.

* Critical item - if marked "NO" contact lab manager.

COMMENTS: _____

NORTHERN

Analytical Laboratories, Inc.

602 South 25th Street
P O Box 30315
Billings, MT 59107
Telephone: (406) 254-7228
Fax: (406) 254-1389

REPORT TO: ATTN: RICHARD LEFERINK
MAXIM TECHNOLOGIES, INC.
P O BOX 4699
HELENA MT 59604

DATE: October 21, 1999
JOB NUMBER: 87-911
SHEET: 1 of 4
INVOICE NO.: 25516346

REPORT OF: Building Material Analysis - Thomas, Dean & Hoskins - Capehart Family Housing #3
#12 Birch Street - 9900589.100

CASE NARRATIVE:

On October 14, 1999, our laboratory received nine building material samples from Richard Leferink. A completed chain of custody record was received which identified the above referenced project as the source of the samples. Our laboratory assigned laboratory numbers 140994 through 141002 to the samples. This analysis was performed using an Olympus BH-2 polarizing microscope at magnifications of 40X to 400X in general accordance with EPA Method 600/R-93/116, July 1993, which employs polarized light microscopic techniques with dispersion staining for identification of mineral forms of asbestos.

There are currently six types of mineral fiber that are regulated as asbestos minerals. These are divided into two categories: serpentine asbestos and amphibole asbestos. Serpentine asbestos is called chrysotile, which is the most commonly encountered type of asbestos in the United States. Five of the asbestos minerals are amphiboles. Included in this group are fibrous grunerite (amosite), fibrous riebeckite (crocidolite), fibrous anthophyllite, fibrous tremolite and fibrous actinolite.

The EPA test method for bulk analysis (EPA/600/R-93/116) states in paragraph 2.2.2. that "the detection limit for visual estimation is a function of the quantity of sample analyzed, the nature of matrix interference, sample preparation, and fiber size and distribution. Asbestos may be detected in concentrations of less than one percent by area if sufficient material is analyzed. Samples may contain fibers too small to be resolved by PLM (<0.25 micrometers in diameter) so detection of those fibers by this method may not be possible".

In the case of nonhomogeneous samples (samples which contain more than one visually distinct material which is not mixed), concentrations of materials are given for each layer and composite values are given for the entire sample. The quantification of asbestos in the sample is intended to be a volume estimate only. The concentrations of various components reported for these samples are intended to represent the materials received at our laboratory for testing only. Variations in the concentrations due to the limitations of the test method, equipment, and operator are given below.

- 1 - 10%, true concentrations may vary $\pm 5\%$ from the reported value
- 10 - 50%, true concentrations may vary $\pm 10\%$ from the reported value
- 50 - 100%, true concentrations may vary $\pm 10\%$ from the reported value

According to the National Emission Standards for Hazardous Air Pollutants; Asbestos NESHAP Revision Final Rule in the Federal Register, Volume 55, Number 224 dated November 20, 1990, any friable material containing less than 10 percent asbestos by the Polarized Light Microscopy (PLM) Method is recommended to be verified by the Point Count Method using PLM. Friable asbestos material means any material containing more than one percent asbestos as determined by the visual PLM method, that when dry can be crumbled, pulverized or reduced to powder with hand pressure. This rule applies to building renovations and demolitions.

As a mutual protection to clients, the public and ourselves, all reports are submitted as the confidential property of our clients and authorization for publication of statements, conclusions or extracts from or regarding our reports is reserved pending our written approval. Test results apply specifically to the samples tested only. The entire report shall not be reproduced, except in full, without the written approval of the laboratory. Samples will be disposed of after testing is completed unless other arrangements are agreed to in writing.

Building Material Analysis
Thomas, Dean & Hoskins - Capehart Family Housing #3
#12 Birch Street - 9900589.100

October 21, 1999
Job No. 87-911
Sheet 2 of 4

The U.S. EPA Clarification of the Asbestos NESHAP Requirement to perform Point Counting dated May 8, 1991 states:

- ◆ First, that a sample which contains no asbestos by visual PLM does not have to be point counted.
- ◆ Second, the owner or operator of the building may choose to assume the asbestos amount to be greater than one percent and treat the material as asbestos containing material (ACM) or require point counting for verification.
- ◆ Third, if a result obtained by point counting is different from a result obtained by visual estimation, the point count result will be used.

We will hold the samples for sixty (60) days in the event you choose to have future analysis performed on any sample containing less than 10 percent asbestos.

The results are shown on the following page. A < sign indicates the value reported was the practical quantitation limit for these samples using the method described. Concentrations of analyte, if present, below this were not quantifiable.

On April 1, 1989, our laboratory was assigned "accredited" status by the National Institute of Standards and Technology's National Voluntary Laboratory Accreditation Program, (NVLAP), Laboratory Code No. 101292-0.

This report may not be used to claim a product endorsement by NVLAP or any agency of the U.S. government.

Analyzed by:

Mike O'neill

Reviewed by:

Carlton ALA

Attachments: Chain of Custody
Sample Receipt Checklist

caj

NORTHERN

Analytical Laboratories, Inc.

BUILDING MATERIAL ANALYSIS ASBESTOS CONTENT

THOMAS, DEAN & HOSKINS - CAPEHART FAMILY HOUSING #3
#12 BIRCH STREET - 9900589.100

October 21, 1999
Job No. 87-911
Sheet 3 of 4

Lab No.	Sample Identification	Sample Description	Asbestos Identification and Estimated Quantity	Non-Asbestos Fibrous Material Identification and Estimated Quantity
140994	M3.1A-Wallboard & Joint compound - Rm 111	Three layers: 1) Gray crystalline solid w/paint (30%) 2) Tan fibrous backing (35%) 3) White chalky solid (35%) Composite of Layers:	3% Chrysotile None Detected None Detected <1% Chrysotile	97% Nonfibrous Binder 90% Cellulose 10% Nonfibrous Binder <1% Cellulose 99% Nonfibrous Binder
140995	M3.1B-Wallboard & Joint compound - Rm 105	Three layers: 1) Gray crystalline solid w/paint (25%) 2) Tan fibrous backing (10%) 3) White chalky solid (65%) Composite of Layers:	3% Chrysotile None Detected None Detected <1% Chrysotile	97% Nonfibrous Binder 90% Cellulose 10% Nonfibrous Binder <1% Cellulose 99% Nonfibrous Binder
140996	M3.1C-Wallboard & Joint compound - Rm 101	Three layers: 1) Gray crystalline solid w/paint (5%) 2) Tan fibrous backing (25%) 3) White chalky solid (70%) Composite of Layers:	3% Chrysotile None Detected None Detected <1% Chrysotile	97% Nonfibrous Binder 90% Cellulose 10% Nonfibrous Binder <1% Cellulose 99% Nonfibrous Binder
140997	M3.2A-Wallboard & Joint compound - Rm 001	Three layers: 1) White crystalline solid w/paint (2%) 2) Tan fibrous backing (8%) 3) White chalky solid (90%)	None Detected None Detected None Detected	100% Nonfibrous Binder 90% Cellulose 10% Nonfibrous Binder <1% Cellulose 99% Nonfibrous Binder
140998	M3.2B-Wallboard & Joint compound - Rm 001	Three layers: 1) White crystalline solid w/paint (2%) 2) Tan fibrous backing (18%) 3) White chalky solid (80%)	None Detected None Detected None Detected	100% Nonfibrous Binder 90% Cellulose 10% Nonfibrous Binder <1% Cellulose 99% Nonfibrous Binder

**BUILDING MATERIAL ANALYSIS
ASBESTOS CONTENT**

**THOMAS, DEAN & HOSKINS - CAPEHART FAMILY HOUSING #3
#12 BIRCH STREET - 9900589.100**

October 21, 1999
Job No. 87-911
Sheet 4 of 4

<u>Lab No.</u>	<u>Sample Identification</u>	<u>Sample Description</u>	<u>Asbestos Identification and Estimated Quantity</u>	<u>Non-Asbestos Fibrous Material Identification and Estimated Quantity</u>
140999	M3.2C-Wallboard & Joint compound - Rm 001	Three layers: 1) White crystalline solid w/paint (25%) 2) Tan fibrous backing (20%) 3) White chalky solid (55%)	None Detected None Detected None Detected	100% Nonfibrous Binder 90% Cellulose 10% Nonfibrous Binder <1% Cellulose 99% Nonfibrous Binder
141000	S1.1A-Surfacing Compound Rm 111	Two layers: 1) Gray crystalline layer w/paint (90%) 2) White fibrous layer (10%) Composite of Layers:	<1% Chrysotile None Detected <1% Chrysotile	99% Nonfibrous Binder & Paint 90% Cellulose 10% Nonfibrous Binder
141001	S1.1B-Surfacing Compound Rm 104	Two layers: 1) Gray crystalline layer w/paint (75%) 2) Tan fibrous backing (25%) Composite of Layers:	3% Chrysotile None Detected 2% Chrysotile	97% Nonfibrous Binder 90% Cellulose 10% Nonfibrous Binder
141002	S1.1C-Surfacing Compound Rm 105	Two layers: 1) Gray crystalline layer w/paint (95%) 2) White fibrous layer (5%) Composite of Layers:	3% Chrysotile None Detected 3% Chrysotile	97% Nonfibrous Binder 90% Cellulose 10% Nonfibrous Binder



SAMPLE RECEIPT CHECKLIST

Dear Valued Client: This checklist documents the condition of your sample(s) as it (they) arrived at our lab. Please review it and familiarize yourself with its contents. Should you have any questions or comments, please contact us. Thank you for your use of our services.

Client Name M-Hellman Date/Time Received 10/14/99 0730
 Project Thomas Dean - Hazard Received by MLW
 Laboratory Number(s) 140988/993 Carrier Name USPS
 Checklist Completed by MLW 10/14/99 Sample Type PLM
Initials / Date

	YES	NO		YES	NO
1. Shipping container in good condition?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	14. pH check performed by: _____		
2. Custody seals present on shipping container? Condition: Intact <input checked="" type="checkbox"/> Broken <input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	15. Metals bottle(s) pH <2?	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Chain of custody present?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	16. Nutrient bottle(s) pH <2?	<input type="checkbox"/>	<input type="checkbox"/>
4. Chain of custody signed when relinquished and received?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	17. Cyanide bottle(s) pH >12?	<input type="checkbox"/>	<input type="checkbox"/>
5. Chain of custody agrees with sample labels?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	18. Sulfide bottle(s) pH >9?	<input type="checkbox"/>	<input type="checkbox"/>
6. Custody seals on sample bottles? Condition: Intact <input type="checkbox"/> Broken <input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	19. TOC bottle(s) pH <2?	<input type="checkbox"/>	<input type="checkbox"/>
7. Samples in proper container/bottle?*	<input checked="" type="checkbox"/>	<input type="checkbox"/>	20. Phenolics bottle(s) pH <2?	<input type="checkbox"/>	<input type="checkbox"/>
8. Sample containers intact?*	<input checked="" type="checkbox"/>	<input type="checkbox"/>	21. Oil & grease bottle(s) pH <2? (checked by analyst)	<input type="checkbox"/>	<input type="checkbox"/>
9. Sufficient sample volume for indicated test?*	<input checked="" type="checkbox"/>	<input type="checkbox"/>	22. DRO/418.1 bottle(s) pH <2? (checked by analyst)	<input type="checkbox"/>	<input type="checkbox"/>
10. Ice/Frozen Blue Ice present in shipping container? (circle one) <u>NA</u>			23. Volatiles (VOA) pH <2? (VOA pH checked by analyst)	<input type="checkbox"/>	<input type="checkbox"/>
container temperature 1. _____ 2. _____ 3. _____ * (if <0 or >10)			24. Herbicides (515) pH <2? (checked by analyst)	<input type="checkbox"/>	<input type="checkbox"/>
11. All samples rec'd within holding time?*	<input checked="" type="checkbox"/>	<input type="checkbox"/>	25. Semivolatiles (525) pH <2? (checked by analyst)	<input type="checkbox"/>	<input type="checkbox"/>
12. VOA vials have zero headspace? * (if contains >5mm headspace)	<input type="checkbox"/>	<input checked="" type="checkbox"/>	26. Client contacted?	<input type="checkbox"/>	<input type="checkbox"/>
13. Trip Blank received?	<input type="checkbox"/>	<input type="checkbox"/>	27. Person contacted	<input type="checkbox"/>	<input type="checkbox"/>
			28. Date contacted	<input type="checkbox"/>	<input type="checkbox"/>

NOTES: Samples may be affected when not transported at the temperature recommended by the EPA for the test you've selected. Please contact the lab if you have concerns about the temperature of your samples.



* Critical item - If marked "NO" contact lab manager.

COMMENTS: _____

APPENDIX D

ASBESTOS HOMOGENEOUS AREA DIAGRAMS

\\scc\y\nd\maxim\11\aspen\color.dwg



LEGEND

- HA-F1.1 Yellow and Tan Linoleum and Mastic (assumed positive)
- HA-F1.2 Tile Pattern Linoleum and Mastic (assumed positive)
- HA-M3.1 Wallboard and Taping Materials
- HA-M12.1 Mastic under 4" Rubber Base (assumed positive)
- HA-S1.1 Surfacing Compound

NOTE: HA-M1.1 - Asphalt Roofing Materials Assumed Positive (not shown)



0 Feet 8


MAXIM 9900589.100

October 1999


ACBM Homogeneous Area Locations
MAFB - 11 Aspen
Great Falls, Montana
FIGURE 1

facility\msm\msm\12asp\floor.dwg


Basement Floor



Main Floor



Upper Floor



LEGEND

- HA-F1.1 Tan and Yellow Linoleum and Mastic (assumed positive)
- HA-F1.2 Orange Linoleum and Mastic (assumed positive)
- HA-S1.1 Surfacing Compound
- HA-M3.1 Wallboard and Taping Materials
- HA-M12.1 Mastic under 4" Rubber Wallbase (assumed positive)

NOTE: HA-M1.1 - Asphalt Roofing Materials Assumed Positive (not shown)




0 Feet 6

MAXIM 9900689.100

October 1999

ACBM Homogeneous Area Locations
MAFB - 12 Aspen
Great Falls, Montana
FIGURE 1

facility:\administrative\2cedar\Floor.dwg



LEGEND

- HA-F1.1 Dark Yellow/Beige Pattern Linoleum and Mastic (assumed positive)
- HA-F1.2 Light Yellow/Beige Pattern Linoleum and Mastic (assumed positive)
- HA-F1.3 Beige Linoleum and Mastic (assumed positive)
- HA-F3.1 9x9" Tan and Gray Floor Tile and Mastic (assumed positive)
- HA-M3.1 Wallboard and Taping Materials
- HA-M12.1 Mastic under 4" Rubber Baseboard (assumed positive)
- HA-S1.1 Surfacing Compound

NOTE: HA-M1.1 - Asphalt Roofing Materials Assumed Positive (not shown)




0 Feet 8

MAXIM 9900569.100

October 1999

ACBM Homogeneous Area Locations
 MAFB - 2 Cedar
 Great Falls, Montana
 FIGURE 1

locality\mlm\slm\2cedr\10ar.dwg



LEGEND

- HA-F1.1 Beige Linoleum and Mastic (assumed positive) and Surfacing Compound
- HA-F1.2 Beige/Grey Linoleum and Mastic (assumed positive)
- HA-M3.1 Wallboard and Taping Materials
- HA-M12.1 Mastic under 4" Black Rubber Vitrabase (assumed positive)
- HA-S1.1 Surfacing Compound

NOTE: HA-M1.1 - Asphalt Roofing Materials Assumed Positive (not shown)



0 Feet 8

MAXIM 9600589.100

October 1999

ACBM Homogeneous Area Locations
MAFB - 12 Birch
Great Falls, Montana
FIGURE 1

This page intentionally blank

APPENDIX E

PHOTOGRAPHS OF HOMOGENEOUS
ASBESTOS-CONTAINING BUILDING MATERIALS



Photo 1 - Front of Residence (#11 Aspen)



Photo 2 - Wallboard and Taping Material (M3.1)



Photo 3 - Surfacing Compound (S1.1)



Photo 1 - Front of Residence (#12 Aspen)




Photo 2 - Wallboard and Taping Material (M3.1)



Photo 3 - Surfacing Compound (S1.1)



Photo 1 - Front of Residence (#2 Cedar)



Photo 2 - Wallboard and Taping Material (M3.1)



Photo 3 - Surfacing Compound (S1.1)



Photo 1 - Front of Residence (#12 Birch)




Photo 2 - Wallboard and Taping Material (M3.1)




Photo 3 - Surfacing Compound (S1.1)

This page intentionally blank

APPENDIX F

LEAD-BASED PAINT XRF TEST
RESULTS

EXPLANATION OF XRF TEST HEADINGS

Positive LHA-NO. refers to painted building components that are grouped together into homogeneous areas (LHAs) based on specific component type and substrate material.

The **Room #** refers to the room number given to the room by the inspector - not necessarily the room number shown on the doors in the building.

The **Side** heading refers to sides of the building. The outside of the building is lettered starting with the letter A. The A side of the building refers to the side in which the building gets its address, or in cases where there is no address it refers to the side where the front entrance is located. Then starting at the A side, the building is lettered consecutively B, C, D clockwise around the building. Inside the building, the rooms are labeled in the same manner.

The **Structure** heading refers to the actual structure being tested, such as a window, wall, or handrail.

The **Feature** refers to a part of the structure where the actual test was taken. For example, on a window the XRF may be held on the sash, the mullions or the casing. Features are assigned by the Niton in the field to ensure accuracy and displayed on the XRF Test Result Sheets. Features include doors, window sash ("sash"), window stools (a window component), and other building components.

The **Fea#** heading gives a location on features where the XRF reading was taken since different features on a structure may be painted with different paints, some possibly containing lead, others not.

The **Substrate** heading tells what the painted structure or feature is made of.

The **Lead Concentration (in mg/cm²)** is the XRF measurement of the concentration (milligrams) of lead per square centimeter (cm²) of a painted surface. According to HUD, the level of lead in paint or other coatings which materially endangers the health of children or adults by producing a substantial and serious danger of lead poisoning is a measurement of 1.0 mg/cm² or greater as measured by X-Ray Florescence (XRF).

The **Depth** is the XRF measurement of the depth of the layer or layers of paint corresponding to confidence intervals constructed by the XRF. The Niton XL ARF Depth Index, a scale from 1 - 10, 10 being deeply buried lead, provides for concentration calculations of: 1.0 mg/cm², plus or minus 0.15 mg/cm² for surface lead; plus or minus 0.2 mg/cm² for buried lead; plus or minus 0.3 mg/cm² for deeply buried lead, for all substrates at 95% confidence. The depth index is explained as follows: 1-3.0 for surface lead; 3.1-5.0 for buried lead; and 5.1-10 for deeply buried lead.

XRF Test Results
 #11 Aspen Street
 MAFB
 Great Falls, Montana
 Niton XL #309-U638NR154

<u>Positive</u> <u>LHA-NO</u>	<u>Room#</u>	<u>Side</u>	<u>Structure</u>	<u>Feature</u>	<u>Fea#</u>	<u>Substrate</u>	<u>Pb</u> <u>mg/cm2</u>	<u>Depth</u>
	101	A	Wall	Middle Wall		Drywall	<0.1	2.6
	101	A	Ceiling	Ceiling		Drywall	<0.1	4.7
	101	A	Window	Mullion		Wood	<0.1	1
26A	101	A	Wall	Baseboard		Wood	1.07	3.5
	101	A	Shelves	Closet		Wood	<0.1	1.7
	101	A	Shelves	Closet		Wood	<0.1	1
	101	A	Radiator	Radiator		Metal	0.13	5.5
	102	A	Wall	Middle Wall		Drywall	0.46	5.3
	102	A	Radiator	Radiator		Metal	0.4	3.3
	102	A	Ceiling	Ceiling		Drywall	0.19	3
	103	A	Wall	Wall	Upr	Drywall	0.25	9.3
14F	103	A	Door	Door		Wood	2.04	10
17F	103	A	Door	Jamb	Left	Wood	1.19	2
	103	A	Door	Casing	Left	Wood	0.13	3.2
26A	103	A	Wall	Baseboard		Wood	0.81	6.2
	102	A	Radiator	Radiator		Metal	<0.1	2.6
	104	A	Door	Jamb	Left	Wood	0.27	3.4
	104	A	Door	Casing	Left	Wood	0.14	2.3
26A	104	A	Wall	Baseboard		Wood	1.77	4.9
	105	A	Stairway	Step		Wood	<0.1	1
	105	A	Stairway	Stringer		Wood	<0.1	1
	105	A	Ceiling	Ceiling		Drywall	0.29	3.1
	105	A	Wall	Wall	Upr	Drywall	<0.1	1
	105	A	Wall	Wall	Lwr	Concrete	0.19	1.9
	105	A	Stairway	Step		Wood	0.2	2.2
	105	A	Stairway	Stringer		Wood	0.38	2.7
	001	A	Ceiling	Ceiling		Drywall	0.16	1
	001	A	Wall	Middle Wall		Concrete	0.33	3.5
	001	A	Floor	Floor		Concrete	<0.1	1
	001	A	Floor	Floor		Concrete	<0.1	1.1
	001	A	Wall	Wall	Lwr	Drywall	0.27	3.5
	001	A	Window	Sill	Ext	Wood	0.15	1.4
23A	001	A	Window	Sash	Lwr	Wood	1.19	1.9
	001	A	Columns	Columns		Metal	<0.1	2.9
	001	A	Columns	Columns		Metal	<0.1	5.9
	106	A	Floor	Floor		Wood	<0.1	1
	106	A	Wall	Middle Wall		Wood	<0.1	1
	107	A	Door	Jamb	Left	Wood	0.26	3.6
	107	A	Door	Casing	Left	Wood	0.1	2.6
	107	A	Window	Sash	Lwr	Wood	<0.1	1
	107	A	Radiator	Radiator		Metal	0.15	3.4
	108	A	Wall	Middle Wall		Drywall	<0.1	1
	108	A	Shelf	Holder		Wood	0.1	4.8
	105	A	Ceiling	Ceiling		Drywall	<0.1	1
	109	A	Window	Mullion		Wood	<0.1	1.4
26A	109	A	Wall	Baseboard		Wood	0.75	8.2

XRF Test Results
 #11 Aspen Street
 MAFB
 Great Falls, Montana
 Niton XL #309-U638NR154

<u>Positive</u> <u>LHA-NO</u>	<u>Room#</u>	<u>Side</u>	<u>Structure</u>	<u>Feature</u>	<u>Fea#</u>	<u>Substrate</u>	<u>Pb</u> <u>mg/cm2</u>	<u>Depth</u>
	109	A	Radiator	Radiator		Metal	<0.1	1.4
	110	A	Window	Stool		Wood	0.24	2.8
	110	A	Wall	Baseboard		Wood	<0.1	1
	111	A	Shelf	Holder		Wood	<0.1	1
	113	A	Door	Jamb	Left	Wood	<0.1	2
	113	A	Door	Jamb	Rht	Wood	<0.1	2.3
	113	A	Window	Sill	Ext	Wood	<0.1	1
26A	113	A	Wall	Baseboard		Wood	0.76	4.1
	115	A	Shelf	Holder		Wood	<0.1	1
	116	A	Radiator	Radiator		Metal	0.11	4.2
	EXT	A	Handrail	Handrail		Metal	0.21	1.2
	EXT	A	Handrail	Handrail		Metal	0.1	1
	EXT	A	Downspout	Downspout		Metal	<0.1	3.1
	EXT	A	Downspout	Downspout		Metal	<0.1	1.7
59F	EXT	A	Soffit	Soffit		Wood	>5.09	3.4
	EXT	A	Columns	Columns		Wood	<0.1	1
	EXT	A	Columns	Columns		Wood	<0.1	1
23A	EXT	A	Window	Sash	Ext	Wood	3.73	3.2
	EXT	A	Ext Wall	Siding		Metal	<0.1	6.9
	EXT	A	Ext Wall	Siding		Metal	<0.1	10
	EXT	A	Soffit	Soffit		Metal	<0.1	1
	EXT	A	Soffit	Soffit		Metal	<0.1	6.7
	EXT	A	Door	Door		Metal	<0.1	3
	EXT	A	Door	Jamb		Metal	<0.1	1
23A	EXT	A	Window	Sash	Ext	Wood	>5.09	4.1
	EXT	A	Door	Door		Wood	<0.1	1
	EXT	A	Door	Jamb		Metal	0.34	10
	EXT	A	Door	Threshold		Wood	<0.1	1
	EXT	A	Door	Jamb		Metal	<0.1	5.3
23A	EXT	A	Window	Sash	Ext	Wood	3.5	4.8

XRF Test Results
 #12 Aspen Street
 MAFB
 Great Falls, Montana
 Niton XL #309-U638NR154

<u>Positive</u> <u>LHA-NO</u>	<u>Room#</u>	<u>Side</u>	<u>Structure</u>	<u>Feature</u>	<u>Fea#</u>	<u>Substrate</u>	<u>Pb</u> <u>mg/cm2</u>	<u>Depth</u>
	101	A	Wall	Middle Wall		Drywall	0.08	2.3
14A	101	A	Door	Door		Wood	1.6	3.6
	101	A	Door	Casing	Left	Wood	<0.1	2
17A	101	A	Door	Jamb	Rht	Wood	0.85	2.5
	101	A	Window	Stool		Wood	0.12	1.9
	101	A	Window	Mullion		Wood	<0.1	1.1
	101	A	Window	Casing	Left	Wood	<0.1	1.1
26A	101	A	Wall	Baseboard		Wood	0.86	3
	101	A	Radiator	Radiator		Metal	<0.1	2.2
	102	A	Ceiling	Ceiling		Drywall	<0.1	1.6
	102	A	Wall	Middle Wall		Drywall	0.24	4
14A	102	A	Door	Door		Wood	2.26	2.8
17A	102	A	Door	Jamb	Left	Wood	1.37	2.5
	102	A	Door	Casing	Left	Wood	<0.1	1.4
	102	A	Window	Sash	Lwr	Wood	<0.1	1
	102	A	Window	Casing	Left	Wood	0.11	2.4
	103	A	Wall	Middle Wall		Drywall	<0.1	1.9
	103	A	Ceiling	Ceiling		Drywall	0.1	2.1
	103	A	Door	Jamb	Left	Wood	0.16	1.9
	103	A	Door	Casing	Left	Wood	<0.1	2.1
	103	A	Window	Casing	Rht	Wood	<0.1	2.4
	104	A	Wall	Middle Wall		Drywall	0.14	3.8
	104	A	Ceiling	Ceiling		Drywall	<0.1	1
	104	A	Stairs	Stringer		Wood	0.72	2.9
	104	A	Stairs	Stringer		Wood	0.57	2.5
	201	A	Wall	Wall	Upr	Drywall	<0.1	2.1
	201	A	Ceiling	Ceiling		Drywall	<0.1	1.5
	201	A	Door	Jamb	Left	Wood	<0.1	1.3
	201	A	Door	Casing	Left	Wood	0.15	2.2
	201	A	Window	Sill	Ext	Wood	<0.1	2
26A	201	A	Wall	Baseboard		Wood	<0.1	1
	202	A	Ceiling	Ceiling		Drywall	0.12	2.2
	203	A	Wall	Middle Wall		Wood	<0.1	1
	203	A	Wall	Wall		Wood	<0.1	1
	204	A	Window	Mullion		Wood	0.36	3.3
	204	A	Radiator	Radiator		Metal	<0.1	1.4
26A	204	A	Wall	Baseboard		Wood	0.87	2.3
	204	A	Door	Jamb	Left	Wood	<0.1	1.2
	204	A	Door	Casing	Left	Wood	0.16	2.1
26A	204	A	Wall	Baseboard		Wood	0.97	2.4
	205	A	Shelves	Closet		Wood	<0.1	1.5
	205	A	Shelves	Closet		Wood	<0.1	1
	206	A	Wall	Middle Wall		Drywall	<0.1	3.9
26A	206	A	Wall	Baseboard		Wood	0.68	2.4

XRF Test Results
 #12 Aspen Street
 MAFB
 Great Falls, Montana
 Niton XL #309-U638NR154

<u>Positive LHA-NO</u>	<u>Room#</u>	<u>Side</u>	<u>Structure</u>	<u>Feature</u>	<u>Fea#</u>	<u>Substrate</u>	<u>Pb mg/cm²</u>	<u>Depth</u>
	206	A	Radiator	Radiator		Metal	<0.1	1
	209	A	Ceiling	Ceiling		Drywall	<0.1	1
	209	A	Wall	Middle Wall		Drywall	0.1	2.6
	209	A	Door	Jamb	Left	Wood	0.12	2
	209	A	Door	Casing	Left	Wood	0.13	2.2
	209	A	Window	Mullion		Wood	<0.1	1
26A	209	A	Wall	Baseboard		Wood	2.05	3.4
	209	A	Radiator	Radiator		Metal	<0.1	3.2
	210	A	Shelves	Closet		Wood	<0.1	1
	210	A	Floor	Floor		Wood	<0.1	1
	210	A	Floor	Floor		Wood	<0.1	1
33I	EXT	A	Handrail	Handrail		Metal	>5.09	1.9
	EXT	A	Ext Wall	Siding		Metal	<0.1	3.2
	EXT	A	Door	Door		Metal	<0.1	1
	EXT	A	Door	Jamb		Metal	0.34	9.3
	EXT	A	Columns	Columns		Wood	<0.1	1
	EXT	A	Columns	Columns		Wood	<0.1	1
	EXT	A	Rain	Gutters		Metal	<0.1	1
	EXT	A	Rain	Gutters		Metal	0.18	1.7
46A	EXT	A	Soffit	Soffit		Wood	3.75	2.9
	EXT	A	Soffit	Soffit		Metal	0.49	10
46A	EXT	A	Soffit	Soffit		Wood	>5.09	4.2
	EXT	A	Window	Sash	Ext	Wood	0.53	2.7
	EXT	A	Downspout	Downspout		Metal	<0.1	1.4
	EXT	A	Downspout	Downspout		Metal	<0.1	1
14B	EXT	A	Door	Door		Wood	>5.09	2.4
17A	EXT	A	Door	Jamb		Wood	2.62	1.5
	105	A	Stairway	Edge		Wood	<0.1	1
	105	A	Foundation	Wall		Wood	<0.1	1
	105	A	Stairs	Tread		Wood	<0.1	1
	105	A	Stairs	Stringer		Wood	<0.1	1.2
	001	A	Wall	Middle Wall		Concrete	<0.1	1
	001	A	Wall	Middle Wall		Concrete	<0.1	1
	001	A	Window	Sash	Lwr	Wood	0.64	1.4
23A	001	A	Window	Storm	Ext	Wood	2.92	3.2
	001	A	Window	Casing	Rht	Wood	<0.1	1
23A	001	A	Window	Storm	Ext	Wood	1.37	1.2
14A	102	A	Door	Door		Wood	2.04	6.8
17A	201	A	Door	Jamb	Left	Wood	1.54	3.7
	102	A	Door	Casing	Left	Wood	0.36	2.7
	102	A	Window	Sill	Ext	Wood	0.36	3.1

XRF Test Results
 #2 Cedar Street
 MAFB
 Great Falls, Montana
 Niton XL #309-U638NR154

<u>Positive</u> <u>LHA-NO</u>	<u>Room#</u>	<u>Side</u>	<u>Structure</u>	<u>Feature</u>	<u>Fea#</u>	<u>Substrate</u>	<u>Pb</u> <u>mg/cm2</u>	<u>Depth</u>
	EXT	A	Rain Gutter	Rain Gutter		Metal	<0.1	1
	EXT	A	Rain Gutter	Rain Gutter		Metal	<0.1	5.6
	EXT	A	Downspout	Downspout		Metal	<0.1	2.8
	EXT	A	Downspout	Downspout		Metal	<0.1	1
	EXT	A	Soffit	Soffit		Metal	<0.1	1.5
	EXT	A	Soffit	Soffit		Metal	<0.1	3.2
55C	EXT	A	Soffit	Soffit		Wood	>5.09	3.9
55C	EXT	A	Beam	Beam		Wood	4.31	3.3
	EXT	A	Ext Wall	Siding		Metal	<0.1	2.4
	EXT	A	Ext Wall	Siding		Metal	<0.1	10
	EXT	A	Columns	Columns		Wood	<0.1	7.4
	EXT	A	Columns	Columns		Wood	<0.1	1
	EXT	A	Window	Sash	Ext	Wood	<0.1	1
23D	EXT	A	Window	Sash	Ext	Wood	>5.09	4.2
33I	EXT	A	Handrail	Handrail		Metal	>5.09	1.3
	EXT	A	Door	Door		Metal	<0.1	1
	EXT	A	Door	Jamb		Metal	<0.1	1
	EXT	A	Door	Door		Metal	<0.1	1.7
	EXT	A	Door	Door		Metal	<0.1	1
	EXT	A	Door	Jamb		Metal	<0.1	1
	EXT	A	Door	Jamb		Metal	<0.1	1
14C	EXT	A	Door	Door		Wood	2.37	10
	EXT	A	Door	Threshold		Wood	<0.1	2.4
17D	EXT	A	Door	Jamb		Wood	2.01	4
23D	EXT	A	Window	Sash	Ext	Wood	3.37	3.5
	101	A	Ceiling	Ceiling		Drywall	<0.1	1.6
	101	A	Wall	Middle Wall		Drywall	<0.1	1
	101	A	Door	Door		Wood	<0.1	1
	101	A	Door	Door		Wood	<0.1	1
17A	101	A	Door	Jamb	Left	Wood	1.02	2.9
17A	101	A	Door	Casing	Left	Wood	0.7	6.8
	101	A	Door	Casing	Rht	Wood	<0.1	2.1
	101	A	Window	Sill	Ext	Wood	0.15	4.6
26A	101	A	Wall	Baseboard		Wood	0.76	4.8
	101	A	Radiator	Radiator		Metal	0.03	2.1
	102	A	Ceiling	Ceiling		Drywall	<0.1	1
	102	A	Wall	Middle Wall		Drywall	0.1	2.8
	102	A	Door	Door		Metal	0.01	2.7
	102	A	Door	Jamb	Left	Wood	<0.1	1
	102	A	Door	Jamb	Left	Wood	<0.1	1
	102	A	Door	Door		Metal	<0.1	1
	102	A	Door	Casing	Left	Wood	<0.1	1
	102	A	Window	Mullion		Wood	0.14	2.3
	105	A	Wall	Wall	Upr	Drywall	<0.1	1
	105	A	Wall	Wall	Lwr	Concrete	<0.1	1.7

XRF Test Results
 #2 Cedar Street
 MAFB
 Great Falls, Montana
 Niton XL #309-U638NR154

<u>Positive</u> <u>LHA-NO</u>	<u>Room#</u>	<u>Side</u>	<u>Structure</u>	<u>Feature</u>	<u>Fea#</u>	<u>Substrate</u>	<u>Pb</u> <u>mg/cm2</u>	<u>Depth</u>
	105	A	Ceiling	Ceiling		Drywall	0.14	10
	105	A	Stair	Stringer		Wood	<0.1	1
	105	A	Stair	Tread		Wood	0.44	4.5
	105	A	Door	Jamb	Left	Wood	<0.1	2.4
	105	A	Door	Casing	Left	Wood	0.73	2.5
	105	A	Stairwell	Wall		Wood	<0.1	1.1
	105	A	Molding	Wall		Wood	0.24	9.3
	001	A	Ceiling	Ceiling		Wood	<0.1	1
	001	A	Ceiling	Ceiling		Wood	<0.1	1
	001	A	Wall	Middle Wall		Concrete	0.13	2.2
	001	A	Wall	Wall	Upr	Concrete	<0.1	1
23A	001	A	Window	Stool		Wood	1.5	6.4
	001	A	Wall	Baseboard		Wood	<0.1	1
	001	A	Wall	Baseboard		Wood	<0.1	1
	001	A	Hatch	Door		Wood	0.34	1.6
	001	A	Hatch	Door		Wood	<0.1	1
57A	001	A	Hatch	Door		Metal	>5.09	1.9
	103	A	Ceiling	Ceiling		Drywall	<0.1	1.7
	103	A	Wall	Middle Wall		Drywall	<0.1	1
	103	A	Door	Door		Metal	<0.1	3.1
	103	A	Door	Jamb	Left	Wood	<0.1	1
	103	A	Door	Jamb	Left	Wood	<0.1	1
	103	A	Door	Casing	Left	Wood	<0.1	1
26A	103	A	Wall	Baseboard		Wood	0.94	2.3
	104	A	Shelves	Holder		Wood	<0.1	1
	106	A	Door	Jamb	Left	Wood	0.46	7.1
26A	106	A	Wall	Baseboard		Wood	0.86	5.5
	106	A	Door	Casing	Left	Wood	0.68	5.9
	107	A	Window	Sill	Ext	Wood	<0.1	1.6
	107	A	Radiator	Radiator		Metal	<0.1	1
	108	A	Shelves	Holder		Wood	<0.1	1
	108	A	Wall	Baseboard		Wood	0.65	3.9
	109	A	Radiator	Radiator		Metal	<0.1	1.4
	109	A	Window	Sill	Ext	Wood	<0.1	1.7
	109	A	Door	Jamb	Left	Wood	<0.1	1
20A	109	A	Door	Casing	Left	Wood	0.93	7.1
	109	A	Ceiling	Ceiling		Drywall	<0.1	2
	109	A	Wall	Middle Wall		Drywall	0.25	5.7
	110	A	Door	Jamb	Left	Wood	<0.1	1
	110	A	Door	Casing	Left	Wood	0.64	5.7
	110	A	Window	Stops	Left	Wood	0.27	2.4
26A	110	A	Wall	Baseboard		Wood	1.22	3.6
	110	A	Radiator	Radiator		Metal	0.12	3.7
	111	A	Unlisted			Wood	<0.1	1.4
	116	A	Floor	Floor		Wood	<0.1	1.1
	116	A	Ceiling	Ceiling		Wood	<0.1	1

XRF Test Results
 #2 Cedar Street
 MAFB
 Great Falls, Montana
 Niton XL #309-U638NR154

<u>Positive</u> <u>LHA-NO</u>	<u>Room#</u>	<u>Side</u>	<u>Structure</u>	<u>Feature</u>	<u>Fea#</u>	<u>Substrate</u>	<u>Pb</u> <u>mg/cm2</u>	<u>Depth</u>
	101	A	Wall	Middle Wall		Drywall	0.3	4.9
26A	101	A	Wall	Baseboard		Wood	0.76	2.9
	101	A	Radiator	Radiator		Metal	0.15	3.3
	101	A	Window	Sill	Ext	Wood	0.35	4.5
	104	A	Ceiling	Ceiling		Drywall	0.15	3.7
	104	A	Wall	Wall	Lwr	Drywall	0.11	2.1
	104	A	Door	Door		Metal	<0.1	1
	104	A	Door	Jamb	Left	Wood	<0.1	1
	104	A	Door	Casing	Left	Wood	<0.1	1
	104	A	Door	Jamb	Left	Wood	<0.1	1
	104	A	Wall	Baseboard		Wood	0.44	4.2
	103	A	Unlisted	Unlisted		Wood	0.13	1.3

XRF Test Results
 #12 Birch Street
 MAFB
 Great Falls, Montana
 Niton XL #309-U638NR154

<u>Positive</u> <u>LHA-NO</u>	<u>Room#</u>	<u>Side</u>	<u>Structure</u>	<u>Feature</u>	<u>Fea#</u>	<u>Substrate</u>	<u>Pb</u> <u>mq/cm2</u>	<u>Depth</u>
	105	A	Wall	Middle Wall		Drywall	0.2	3.8
	105	A	Ceiling	Ceiling		Drywall	0.28	5
	105	A	Door	Jamb	Left	Wood	0.1	1.4
	105	A	Door	Casing	Left	Wood	0.32	4.8
26A	105	A	Wall	Baseboard		Wood	1.46	3.7
	107	A	Ceiling	Ceiling		Wood	<0.1	2
	107	A	Window	Sill	Ext	Wood	0.21	4.2
	107	A	Radiator	Radiator		Metal	<0.1	2.2
	108	A	Ceiling	Ceiling		Wood	0.33	2.2
	108	A	Floor	Floor		Wood	0.38	1.8
	109	A	Ceiling	Ceiling		Drywall	<0.1	1
	109	A	Wall	Middle Wall		Drywall	<0.1	1
	109	A	Door	Jamb	Left	Wood	0.14	2.1
	109	A	Door	Casing	Left	Wood	0.19	3.6
	109	A	Window	Sill	Ext	Wood	0.15	2.4
26A	109	A	Baseboard	Baseboard		Wood	1.11	4.1
	109	A	Radiator	Radiator		Wood	<0.1	1
	117	A	Door	Jamb	Left	Wood	<0.1	1.3
	117	A	Door	Casing	Left	Wood	<0.1	1.4
	117	A	Window	Sash	Upr	Wood	<0.1	1.6
	117	A	Radiator	Radiator		Metal	0.27	7.8
	118	A	Ceiling	Ceiling		Drywall	<0.1	1
	118	A	Wall	Wall	Lwr	Drywall	<0.1	1.8
	118	A	Wall	Wall	Lwr	Concrete	0.14	9.1
	118	A	Wall	Wall	Lwr	Concrete	<0.1	4.9
	118	A	Unlisted	Unlisted		Wood	<0.1	1.1
	118	A	Stairwell	Molding		Wood	<0.1	2.5
	001	A	Ceiling	Ceiling		Drywall	<0.1	3.3
	001	A	Ceiling	Ceiling		Drywall	<0.1	4.9
	001	A	Wall	Middle Wall		Drywall	<0.1	1
	001	A	Wall	Middle Wall		Drywall	<0.1	1
	001	A	Ceiling	Ceiling		Wood	<0.1	1
	001	A	Ceiling	Ceiling		Wood	<0.1	1
23A	001	A	Window	Sash	Lwr	Wood	1.03	1.2
	001	A	Wall	Baseboard		Wood	<0.1	1
	001	A	Wall	Baseboard		Wood	<0.1	1
	002	A	Wall	Middle Wall		Concrete	0.17	8
	002	A	Wall	Middle Wall		Concrete	<0.1	1
23F	002	A	Window	Sash	Lwr	Wood	1.05	1.5
55C	EXT	A	Beams	Beams		Wood	4.43	3.1
55C	EXT	A	Soffit	Soffit		Wood	>5.09	2.5
	EXT	A	Soffit	Soffit		Metal	0.11	3.2
	EXT	A	Soffit	Soffit		Metal	0.39	10
33I	EXT	A	Handrail	Handrail		Metal	>5.09	1.2

XRF Test Results
 #12 Birch Street
 MAFB
 Great Falls, Montana
 Niton XL #309-U638NR154

<u>Positive</u> <u>LHA-NO</u>	<u>Room#</u>	<u>Side</u>	<u>Structure</u>	<u>Feature</u>	<u>Fea#</u>	<u>Substrate</u>	<u>Pb</u> <u>mg/cm2</u>	<u>Depth</u>
	EXT	A	Unlisted	Unlisted		Wood	<0.1	1
	EXT	A	Unlisted	Unlisted		Wood	<0.1	1
	EXT	A	Downspout	Downspout		Metal	<0.1	1.1
	EXT	A	Downspout	Downspout		Metal	<0.1	1
	EXT	A	Door	Door		Metal	<0.1	1
	EXT	A	Door	Door		Metal	<0.1	1
	EXT	A	Door	Jamb		Metal	<0.1	7.9
	EXT	A	Door	Jamb		Metal	<0.1	1
14A	EXT	A	Door	Door		Wood	2.73	3.9
17A	EXT	A	Door	Jamb		Wood	3.31	3.6
	EXT	A	Ext Wall	Siding		Metal	<0.1	10
	EXT	A	Ext Wall	Siding		Metal	<0.1	7.7
	EXT	A	Window	Sash	Ext	Wood	0.19	1.3
23D	EXT	A	Window	Sill	Ext	Wood	2.67	3.7
	EXT	A	Door	Door		Wood	<0.1	1
17D	EXT	A	Door	Jamb		Wood	0.65	4
	EXT	A	Door	Jamb		Metal	<0.1	1
	EXT	A	Door	Door		Wood	<0.1	1
	EXT	A	Floor	Floor		Wood	<0.1	1
	EXT	A	Floor	Floor		Wood	<0.1	1.6
	EXT	A	Wall	Middle Wall		Drywall	<0.1	1
	EXT	A	Ceiling	Ceiling		Drywall	<0.1	4.8
	EXT	A	Unlisted	Unlisted		Wood	<0.1	1
48C	EXT	A	Wall	Baseboard		Wood	1.27	3.2

This page intentionally blank


APPENDIX G

LEAD-BASED PAINT HOMOGENEOUS
AREA DIAGRAMS



LEGEND

- LHA 14F & 17F
- LHA 23A
- LHA 26A
- LHA 59F
- White Wood Door and Door Jamb
- White Wood Window
- White Wood Baseboard
- Green Wood Soffit and Beams



0 Feet 8


MAXIM 9900589.100

October 1999


LBP Homogeneous Area Locations
MAFB - 11 Aspen
Great Falls, Montana
FIGURE 2

facility\ndmin\atmm\12\aspen\Floor.dwg


Basement Floor



Main Floor



Upper Floor



LEGEND

- LHA 14B & 17A Cream Wood Door and White Wood Jamb
- LHA 14A & 17A White Wood Door and Door Jamb
- LHA 23A White Wood Window
- LHA 26A White Wood Baseboard
- LHA 331 Black Metal Handrail
- LHA 46A White Wood Soffit and Beams




0 Feet 6

MAXIM 9900589.100

October 1999

LBP Homogeneous Area Locations
 MAFB - 12 Aspen
 Great Falls, Montana
FIGURE 2

facility\mmaxim\zooder\Floor.dwg



LEGEND

- | | | | |
|---|---------------|---|-------------------------------------|
|  | LHA 14C & 17D |  | Ten Wood Door and Brown Wood Jamb |
|  | LHA 17A |  | White Wood Door Jamb |
|  | LHA 20A |  | White Wood Door Case |
|  | LHA 23A |  | White Wood Window |
|  | LHA 23D |  | Brown Wood Window |
|  | LHA 26A |  | White Wood Baseboard |
|  | LHA 33I |  | Black Metal Handrail |
|  | LHA 55C |  | Ten Wood Soffit and Beams |
|  | LHA 57A |  | White Metal Crawlspace Access Hatch |





0 Feet 8

MAXIM 9900689.100

October 1999

LBP Homogeneous Area Locations
MAFB - 2 Cedar
Great Falls, Montana
FIGURE 2



LEGEND

- LHA 14A & 17A White Wood Door and Jamb
- LHA 17D Brown Wood Door Jamb
- LHA 23A White Wood Window
- LHA 23D Brown Wood Window
- LHA 23F Green Wood Window
- LHA 26A White Wood Baseboard
- LHA 33I Black Metal Handrail
- LHA 37C & 55C Tan Wood Soffit and Beams



0 Feet 0

MAXIM 9900559.100

October 1999

LBP Homogeneous Area Locations
MAFB - 12 Birch
Great Falls, Montana
FIGURE 2

This page intentionally blank

APPENDIX H

PHOTOGRAPHS OF HOMOGENEOUS
LEAD-BASED PAINTED BUILDING MATERIALS



Photo 1 - Front of Residence (#11 Aspen)



Photo 2 - Green Wood Door and Door Jamb (LHA-14F & 17F)



Photo 3 - White Wood Window (LHA-23A)




Photo 4 - White Wood Baseboard (LHA-26A)



Photo 5 - Green Wood Soffit and Beams (LHA-59F)



Photo 1 - Front of Residence (#12 Aspen)



Photo 2 - Cream Wood Door and White Wood Door Jamb
(LHA-14B & 17A)



Photo 3 - White Wood Door and Door Jamb (LHA-14A &17A)



Photo 4 - White Wood Window (LHA-23A)



Photo 5 - White Wood Baseboard (LHA-26A)



Photo 6 - Black Metal Handrail (LHA-33I)



Photo 7 - White Wood Soffit and Beams (LHA-46A)



Photo 1 - Front of Residence (#2 Cedar)



Photo 2 - Tan Wood Door and Brown Wood Door Jamb
(LHA-14C & 17D)



Photo 3 - White Wood Door Jamb (LHA-17A)



Photo 4 - Brown Wood Window (LHA-23D)



Photo 5 - White Wood Baseboard (LHA-26A)



Photo 6 - Black Metal Handrail (LHA-33I)

NO PHOTO AVAILABLE

Photo 9 - White Wood Window (LHA-23A)

NO PHOTO AVAILABLE

Photo 10 - White Wood Door Casing (LHA-20A)




Photo 1 - Front of Residence (#12 Birch)




Photo 2 - White Wood Door and Door Jamb (LHA-14A & 17A)



Photo 3 - Brown Wood Door Jamb (LHA-17D)

Photo Not Available

Photo 4 - White Wood Window (LHA-23A)



Photo 5 - Brown Wood Window (LHA-23D)

Photo Not Available

Photo 6 - Green Wood Window (LHA-23F)




Photo 7 - White Wood Baseboard (LHA-26A)



Photo 8 - Black Metal Handrail (LHA-331)



Photo 9 - Tan Wood Soffit (LHA-55C)