

Berms/Dikes Report

Reference #	Date Verified	County	Waterbody	Length (feet)	Condition	Notes
JM Resources, LLC						
NWS-2007-1394-A	12/1/2016	Thurston	Totten Inlet	401.48	Good	External dike
				600	Good	Access Berm (approximate length)
				189.45	Good	Internal dike
				212.52	Good	External dike
				186.21	Good	External dike
				238.26	Good	External dike
				900	Good	Access berm (approximate length)
				188.95	Good	Internal dike
				411.08	Good	Internal dike
				384.37	Good	External dike
				203.19	Good	External dike
		Total Count	11	Total Length	3915.51	
Lynden Shellfish						
NWS-2007-1166	2/27/2017	Thurston	Totten Inlet	456	Good	Existing dike, in place for over 100 years
				405	Good	Existing dike, in place for over 100 years
				56	Good	Existing dike, in place for over 100 years
				45	Good	Existing dike, in place for over 100 years
		Total Count	4	Total Length	962	
Minterbrook Oyster Company						
NWS-2014-0589-A		Pierce	Minter Bay	1212	Poor	Not maintained
		Total Count	1	Total Length	1212	
Nisqually Indian Tribe						
NWS-2007-1391	2/10/2017	Thurston	Henderson Inlet	1717	Good	
		Total Count	1	Total Length	1717	
South Sound Mariculture, LLC						

Reference #	Date Verified	County	Waterbody	Length (feet)	Condition	Notes
NWS-2007-1315	11/2/2016	Mason	Hammersley Inlet	180	Good	Constructed prior to 2000, same as NWS-2010-0453
NWS-2007-1316				170	Good	Constructed prior to 2000
		Total Count	2	Total Length	350	
Taylor Shellfish Farms						
NWS-2008-0521-A	2/1/2017	Thurston	Totten Inlet	4200	Fair	Historic; dikes abut adjacent NWS-2008-0527
NWS-2008-0527-A				2260	Fair	
		Total Count	2	Total Length	6460	
TLCZ Shellfish						
NWS-2010-0453	11/2/2016	Mason	Hammersley Inlet	180	Good	Same as NWS-2007-1315
		Total Count	1	Total Length	180	
		Total Count	22	Total Length	14796.5	