



**Figure 5**  
**Alternative 3 - Plan View**



cross dike



excavated channels



area inundated by  
this alternative



Aerial Photos from WDNR (2000)

