

SPENCER ISLAND ECOSYSTEM RESTORATION  
PUGET SOUND & ADJACENT WATERS  
SNOHOMISH COUNTY, WASHINGTON

---

Appendix A  
Site Photos



**US Army Corps  
of Engineers®**  
Seattle District

---

PUGET SOUND  
NEARSHORE  
ECOSYSTEM RESTORATION PROJECT



*Washington Department of*  
**FISH and WILDLIFE**

## APPENDIX A – SITE PHOTOGRAPHS (AUG. 20, 2024)



Photo A-1. Spencer Island taken from Union Slough facing east toward the middle of the island.



Figure A-2. Spencer Island taken from the Union Slough facing southeast toward the southern cross-dike.



Figure A-3. Vegetation including deciduous trees and Himalayan blackberry present on the Union Slough side of Spencer Island



Figure A-4. Deciduous and coniferous trees present on the Union Slough side of Spencer Island near the northern cross-dike.



Photo A-5. Log pile on the Union Slough side of Spencer Island near the northern third of the Island.



Photo A-6. Existing breach connecting Union Slough to Spencer Island near the northwestern end of the site facing east.



Photo A-7. Existing breach connecting Union Slough to Spencer Island near the northern end of the site facing west.



Photo A-8. Existing channel located south of the southern cross-dike facing east.



Photo A-9. Existing mudflats near the southern end of the island facing east.



Photo A-10. Existing viewing platform on the southwest end of Spencer Island.



Photo A-11. Emergent wetland habitats from the southwest side of the island near the cross-dike facing east.



Photo A-12. Emergent and tidal flat wetlands taken from the cross-dike bridge looking north.



Photo A-13. Looking down from the south side of the cross-dike bridge. High velocities were observed at low tide.



Photo A-14. Steamboat slough breach on the southeast end of the island near the cross-dike and at the bridge crossing to the southern end of Spencer Island.



Photo A-15. The bridge on the southeast side of Spencer Island looking south.



Photo A-16. The bridge located on the southeast end of Spencer Island looking southwest.



Photo A-17. Emergent wetlands taken from the southeast corner of Spencer Island looking north.



Photo A-18. Union Slough taken from the entrance bridge to Spencer Island looking north.